



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004830/Kvy3e2	
			Date: 14/07/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMJ 4081H	Veh. Inspected	FBH 4530U
	Policy No.	D22MTPV01002910	Coverage (\$)	0.00
	Claim No.	CMTD2201728/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	23/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA JUPITER	c.c	134
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	MH355S004DK113845	Colour	PURPLE
	Odometer	42049 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80/90 R17	MICHELIN	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90/80 R17	MICHELIN	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/05/2022	Inspection Date	24/05/2022
	Survey held at	5 SOON LEE STREET #01-38 PIONEER POINT		
	Repairer	CREATION MOTORS		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	