



V-TECH AUTO SERVICE

No.1 Soon Lee St #06-04/05/06/07 Pioneer Centre Singapore 627605
Tel: 62646211, 62646222 Fax: 62646233 Email: vtech.autoservice@gmail.com
Reg. 52949633W, GST Reg No. M90364098A 24 HRS TOWING SERVICES
Website: http://vtechauto.com.sg

Vehicle No. YP 2418 K

Parts and Labour Assessment

Description of part

PARTS (LIST ITEMS)

	Qty	Cost
1 FRONT PANEL / <i>DD</i>	1	1,148.10 /
2 FRONT PANEL 300 STICKER / <i>NC</i>	1	45.00 /
3 FRONT PANEL HINO STICKER / <i>NC</i>	1	50.00 /
4 FRONT INNER PANEL / <i>X R</i>	1	887.15 X
5 HEAD LAMP <i>L/R</i> / <i>CNT</i>	1	1,220.00
6 FRONT CENTRE GRILLE ASSY / <i>BR</i>	1	542.20 /
7 FRONT CENTRE GRILLE ASSY LOGO / <i>MS</i>	1	56.00 /
8 AIRCON COOLING PIPE / <i>X BT AN</i>	1	340.00
9 AIRCON DISCHARGE PIPE / <i>BT</i>	1	550.00
10 AIRCON SUCTION PIPE / <i>BT</i>	1	410.00
11 AIRCON DRYER UNIT / <i>X AN</i>	1	118.00
12 AIRCON BLOWER UNIT / <i>X AN</i>	1	893.00
13 AIRCON EVAPORATOR COIL / <i>X AN</i>	1	871.20
14 FRONT BUMPER ASSY / <i>DD</i>	1	981.80 /
15 FRONT BUMPER BRACKET L/R / <i>X AN</i>	2	240.20
16 FRONT BUMPER CENTRE INNER BEAM / <i>DD</i>	1	230.00 /
17 FRONT BUMPER FOG LAMP L/R / <i>X AN</i>	2	420.00

Percentage discount 0%

\$ 9,002.65

\$ -

Sub-total \$ 9,002.65

Water pipe X2 / BT
" " bracket X2 / BT

3663.10
-10%
3296.79

SPECIAL NETT ITEMS

1	FRONT PANEL 'LENG AIK' STICKER / MK	100 /	240.00
2	FRONT GRILLE CLIPS - SET / MK	15 /	30.00
3	FRONT BUMPER NUMBER PLATE ← BT ✓ 00	X	25.00
Sub-total			\$ 295.00

1/5

LABOUR

- 1 To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. 30 / 120.00
- 2 To remove, change dashboard fascia and transfer where necessary. X 200 350.00
- 3 To remove, replaced aircon piping, check evaporator unit, aircon blower motor and etc to vacuum system and top up gas. 150 / 200.00
- 4 To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. 500 / 1,200.00
- 5 To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. 800 / 1,200.00
- 6 To apply anti-rust chemical on repaired and replaced panel. 15/0 30 / 120.00

= 4921.79 Labour Total \$ 3,190.00

Parts & Labour Total \$ 12,487.65

SUPP- 738

5659.79

Best Regards,

Steve (LKK)
14/5/22, 9.30am

00-M AL
EX-11-1

L/S

14 AL 11
5 11

L/S-4527.83
=4550