

Yan (LKK Auto)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, 23 May 2022 9:36 AM
To: assignments; peggy.chan@awac.com
Cc: Reports (LKKAuto); SUR
Subject: FW: Pre-Repair Survey Report of Vehicle SMT 8437L
Attachments: NSV2200008_TPV SMT 8437L.pdf

Importance: High

Dear Peggy,

Thank you for the assignment.

Dear Assignment Team,

FYNA.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Peggy <Peggy.Chan@awac.com>
Sent: Saturday, 21 May 2022 11:08 PM
To: Reports (LKKAuto) <report@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Huey Yon (LKKAuto) <hueyyon@lkkauto.com>; Chan, Peggy <Peggy.Chan@awac.com>
Subject: RE: Pre-Repair Survey Report of Vehicle SMT 8437L
Importance: High

Hi Elaine

We refer to the PRS survey conducted by your surveyor.

We noted your surveyor's recommendation that the repair would be in the region of \$2,000 to \$3,000 and estimated 4 working days for the repair period.

The third party has submitted their claim with quantification and we noted the repair costs was \$7,200 and their surveyor has recommended 7 working days for repairs.

Attached is the survey report and repair invoice for your surveyor to conduct a paper re-adjustment.

Please let us have the paper re-survey report soonest. Thanks.

Regards
Peggy Chan
Assistant Vice President
Asia Pacific Claims Group

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 64230865
F: +65 64230864
E: peggy.chan@awac.com
W: www.awac.com

From: Elaine (LKK Auto) <report@lkkauto.com>
Sent: Friday, 4 February 2022 5:25 PM
To: Motorsurvey <Motorsurvey@awac.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Huey Yon (LKKAuto)' <hueyyon@lkkauto.com>
Subject: Pre-Repair Survey Report of Vehicle SMT 8437L

CAUTION: External Email

Dear Sir / Madam,

Enclose Pre-Repair Survey Report of SMT 8437L.

Thank you.

Best Regards,

Elaine | Reports
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
