

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE L'TD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info				
LONPAC INSURANCE BHD	Cust No/Name	LCV15096/Mr Yeo Chee Tiong (yang Zhizhon			
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706		SLF1459E*#F / 16/08/2016			
	Date In/Mileage 31/05/2022/ 113424				
	Chassis No	KNAFZ411MH5649029			
TEL:02902700	Engine No	G4FGGH638093			
Contact No	Make/Model	KIA/FORTE K3 1.6 A SX HADQ			
	Colour/Trim	B4U / WK			

Account No	Terms	Date/Time	Printed	CSE	Oper	ator	No.	WIP No	A Joseph Visi	
0000040	Credit	02/06/202	22/ 15:34	DS	303	/ Renemer		30145		
		Descripti	on of Goo	ds / Service	S		Qty	Unit Price	Disc%	Amount
S MIPNT880										250.00
	IC/SCANN	ING								00.00
		UTING /LITE	UC CVCTEM	ON DEAD A	CCIDENT	AFFECTED ARE	. 4.0			80.00
S MIPNT880		HITING/WIKI	NO SISIEM	UN KEAR A	CCIDENT	AFFECTED ARE	:A3			1600.00
		EMBLEMS, UP	R & I WR R	FAR BUMPER	.CL TPS .B	RACKETS.				1000.00
	INR TAI				, , , , , , , , ,	,				
TO REPAI	R REAR E	ND PANEL							,	
		M, ALIGN ON	REAR ACC	IDENT AFFE	CTED ARE.	AS				
S MIPNT980										2200.00
		N REAR ACC				on your years	JL_			
		BUMPER, LHR	FENDER &	REAR ENU	PANEL)	m 9	111(8	1		30.00
S MIPNT880 C & C LC			Interpretation of	Mich		11110	IILIC	and any		30.00
M KS 86310		1	OGO ASSY-	KTA SUR	L.I L.I		1.00	44.00	0.00	44.00
KS 86311			MBLEM-CER				1.00	42.00	0.00	42.00
K WFFORTE			ORTE EMBL				1.00	40.00	0.00	40.00
(WFEMBLEM	1K3		MBLEM K3				1.00	15.00	0.00	15.00
KS 86611		U	PR COVER-	REAR BUMPE			1.00	688.00	0.00	688.00
X KS 86695	A7 810			REAR BUMPE			1.00	315.00	0.00	315.00
X KS 86613	8 A7 001	L	H SIDE BR	ACKET-REAR			1.00	29.00	0.00	29.00
X KS 0G032			ASTERNER-				10.00	2.00	0.00	20.00
X KS 92401				P ASSY-REA			1.00	788.00	0.00	788.00
X KS 92403	8 A7 710	L	H INR LAM	P ASSY-REA			1.00	710.00	0.00	710.00
Z NOTES	C ON 01 (0	E/000 ALON	c uppen c	CDANCOON C	I TO DO T	O HOLICANG A	NE 3			
		HIRD PARTY		EKANGOON 3	LIP KU I	O HOUGANG A	VL 3			
LOSS OF		MIKU PAKII								
TP#: GB		TP	INS: LONP	AC						
Z NOTES	173001		THO: LOW	710						
	ON) NOITA	. OF TOTAL	REPAIR D	AYS - 5 DA	YS)					
		. MARCUS C								
Confirm 0	accorted	by					Parts			2,691.0
Confirm & accepted by						Labour			0.0	
							Standard	Menu		0.0
						Specialist Job Others(Lub, etc)			4,160.0	
					0.0					
						Sundry			0.0	
	- danadau	y and compa					Total (w/c	GST)		6,851.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 1