



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS/ASM22004878/UtcM4 Date: 08/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 552H	Veh. Inspected	FBS 7044D
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S2M041NO	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	24/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA XSR155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3RG4760MK018930	Colour	SILVER
	Odometer	28892 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R17	PIRELLI	8 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/60 R17	PIRELLI	8 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/05/2022	Inspection Date	24/05/2022
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	