

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0377/2022/JT
DATE : 12-May-22
WIP : 23715

VEHICLE NOT IN WORKSHOP. SURVEY TBC
YOUR INSURED VEH NO : PC 8470 T

INDIA INTERNATIONAL INSURANCE Pte Ltd
64 CECIL STREET
#04-00/05-00 IOB BUILDING
SINGAPORE 049711
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG PU JUN, JEFFREY
ADDRESS : BLK 296A BUKIT BATOK ST 22
#32-64
SINGAPORE 651296
TELEPHONE : HP +65 97842101
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5116391180-02
VEHICLE NO : **SMJ 6172 R**
MODEL CODE : HONDA VEZEL
MODEL YEAR : 13/3/2019
ENGINE NO : LEB6742206
CHASSIS NO : RU31322195
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-May-22
PLACE OF ACCIDENT : BLK 435A BUKIT BATOK WEST AVE 5

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 6172 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	80
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$ 480.00	80
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00	150
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$ 200.00	50
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	X
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	700
SUB TOTAL LABOUR CHARGES		: \$ 3,040.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMI 6172 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING. <i>3500</i>	\$ 1,600.00	<i>700</i>
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	<i>100</i>
TOTAL LABOUR CHARGES		: \$ 4,832.00	1860



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 6172 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR LID / DD	1	\$ 1,450.00	912.60 ✓
2	REAR LID WEATHER STRIP X	1	\$ 113.00	
3	REAR LID CHROME TRIM X	1	\$ 425.00	
4	HONDA" EMBLEM X	1	\$ 38.00	
5	"VEZEL" EMBLEM / MC	1	\$ 88.00	70 ✓
6	"HYBRID" EMBLEM / MC	1	\$ 95.00	70 ✓
7	REAR BUMPER - LOWER / DD	1	\$ 1,050.00	829 ✓
8	REAR BUMPER CLIP / MC	8	\$ 5.00	40 ✓
9	REAR BUMPER REFLECTOR LIGHT - LH X NN	1	\$ 88.00	
10	REAR WINDSCREEN X NN	1	\$ 1,375.00	
11	REAR WINDSCREEN MOULDING X / MC	1	\$ 150.00	✓
12	REAR WINDSCREEN SEALANT / MC	S/N	\$ 200.00	40 ✓
13	REAR NO PLATE X NN	S/N	\$ 80.00	
14	SUNDRIES ? X NN		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 5,457.00	2071.60
TOTAL LABOUR CHARGES		:	\$ 4,832.00	-20%
GRAND TOTAL		:	\$ 10,289.00	1657.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Nett - 40

total - 3557.28

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :

ster CLKK)
26/5/22, 7:37

W R
P/P
M R L S
S d/s

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LIKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT