

Date: 24/05/2022
Vehicle No: SNE7128C
Model: HYUNDAI OS KONA HEV 1.6 DCT
Chassis: KMHK281EVNU081923
Reg.Year: 2021

Not Authorized
Phoney Repair
2-3 days

Third Party Insurer: AIG
Third Party Veh No: SMP923Z
Date of Accident: 21/05/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER UPPER	1	<i>12</i> <i>500</i>	\$510.00
2	FRONT BUMPER LOWER	1	<i>12</i> <i>600</i>	\$570.00
3	FRONT HEADLAMP CHROME LH	1	<i>12</i>	\$95.00
4	FRONT HEADLAMP LH	1		\$3,900.00
5	FRONT DAY RUNNING LIGHT LH	1	<i>12</i>	\$900.00
6	FRONT FENDER LH	1		REPAIR
SUB TOTAL				\$5,975.00
LESS 20%				-\$1,195.00
PARTS TOTAL				\$4,780.00

X
✓
✓
✓
✓

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>12</i> \$50.00
S/N TOTAL				\$50.00

✓

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$600.00 *300*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

200
\$600.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

100 \$100.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

200 \$80.00

LABOUR TOTAL \$1,380.00

TOTAL \$6,210.00

KIT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____