

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFX1777M (Insd veh)	Model:	TOYOTA HIACE 2.8 D DX (A)
	GBH7399M (TP veh)		
Date of Accident:	22/05/2022		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		11,396.57
Final Repair Cost	:	\$		4,474.74
Loss of Use	:	\$		320.00
				4.00 days at \$80.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		4,796.74

Is Third Party Workshop GIA Registered?		[X] YES	[] NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u>:	Agreed Liability _____(%)			
B) For <u>GIA Registered Workshop</u>:	BOLA Applicable: Yes/ No BOLA Scenario No: _27_			
BOLA Liability: _____100_____ (%)	Assessed Liability (*): _____ (%)			
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	Goldbell Engineering Pte Ltd	:	\$	4,796.74
2)		:	\$	
3)		:	\$	

JOANNE LEE KHANG MIN

30 Dec
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))