

# AGENT MOTORS

Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road  
159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



Star (LKK)

9/6/22, 10:30am

W PL

PIP, M, R, G

GST Registration No. M2-0000551-1

ESTIMATE



|                                              |                                     |                        |
|----------------------------------------------|-------------------------------------|------------------------|
| Estimate No.<br><b>BG 5405</b>               | Date Estimated<br><b>26/05/2022</b> | Page No. <b>1 of 1</b> |
| Prepared By<br><b>Clement Chia Cher-Yang</b> |                                     |                        |

|                                                                                                     |                                                                                                                                |
|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|
| ESTIMATE REPAIR FOR<br><b>Ang Soh Khim</b><br>Blk 454 Clementi Ave 3<br>#04-550<br>Singapore 120454 | ACCOUNT <b>14356</b><br><b>MS First Capital Insurance Limited</b><br>36 Robinson Road<br>#16-01 City House<br>Singapore 068877 |
|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|

|                              |                                         |                                 |                             |                          |
|------------------------------|-----------------------------------------|---------------------------------|-----------------------------|--------------------------|
| REGN. NO.<br><b>SLH4066A</b> | CHASSIS NO.<br><b>WF0DXXWPCDGC81948</b> | REGN. DATE<br><b>02/11/2016</b> | MODEL<br><b>Mon 2.0 4Dr</b> | MILEAGE<br><b>141406</b> |
|------------------------------|-----------------------------------------|---------------------------------|-----------------------------|--------------------------|

| DESCRIPTION                                                                         | VALUE           |
|-------------------------------------------------------------------------------------|-----------------|
| TO CONDUCT THIRD PARTY CLAIM AGAINST MS FIRST CAPITAL INS(SHB5952P). DOA:12.05.2022 | 0.00            |
| TO REMOVE AND REPLACE REAR BUMPER.                                                  | 600.00          |
| TO REMOVE AND REFIT OR INSTALL PARKING SENSORS.(DRILL HOLE)                         | 120.00          |
| TO SPRAY PAINT REAR BUMPER AND ALL OTHER AFFECTED AREAS.                            | 900.00          |
| TO CONDUCT ECU RE-PROGRAMMING AND CLEARING OF FAULT CODES.(NETT)                    | 600.00          |
| SUNDRIES                                                                            | 100.00          |
| <b>Total Labour 1:</b>                                                              | <b>2,320.00</b> |

  

| PART NUMBER          | DESCRIPTION                       | QTY | PRICE    | DISC  | VALUE           |
|----------------------|-----------------------------------|-----|----------|-------|-----------------|
| DS7317K835KAX        | BUMPER ASSY - REAR, PRIMED        | 1   | 2,200.00 | 10.00 | 1,980.00        |
| WAA                  |                                   |     |          |       |                 |
| DS7317E911ME5        | MOULDING-FOG LIGHT REAR BUMPER    | 1   | 620.00   | 10.00 | 558.00          |
| UAW                  |                                   |     |          |       |                 |
| DS7317A894VEX        | SPOILER - LOWER RR BUMPER, PRIMED | 1   | 469.00   | 10.00 | 422.10          |
| WAA                  |                                   |     |          |       |                 |
| F1CT15K859AA5        | RR SENSOR - PARKING AID SYSTEM    | 2   | 95.00    | 10.00 | 171.00          |
| AK5                  |                                   |     |          |       |                 |
| <b>Total Parts :</b> |                                   |     |          |       | <b>3,131.10</b> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Dispute" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Customer Name & Signature / Company Stamp

Date

|                    |            |                 |
|--------------------|------------|-----------------|
| Labour 1           | S\$        | 2,320.00        |
| Parts              | S\$        | 3,131.10        |
| Labour 2           | S\$        | 0.00            |
| Excess             | S\$        | 0.00            |
| Total GST @ 7%     | S\$        | 381.58          |
| <b>Grand Total</b> | <b>S\$</b> | <b>5,832.68</b> |

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.