

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	006E
Vehicle Details	
Vehicle No.:	GBB3509X
Vehicle to be Exported:	No
Intended Deregistration Date:	27 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE AUTO 3.0L
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1KD1888202
Chassis No.:	JTFHT02P000036010
Maximum Power Output:	-
Open Market Value:	\$26,160.00
Original Registration Date:	07 Jan 2009
First Registration Date:	07 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$1,308.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$14,086.00
COE Rebate Amount:	\$4,536.00
Total Rebate Amount:	\$4,536.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 27 May 2022

OK

P1-S4 Free 12 Lessons

35,000+ Questions, 7500+ Videos and 4500+ Assessments. Start Your 14 Day Free Trial Now
88Tuition

[Sign Up](#)

Post an Advertisement
Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Drive & Feel Like New Honda Civic 1.5A VTEC Turbo



Extremely Powerful And Very Responsive 1.5L Turbocharged Engine With 171BHP!
WS Car Pte Ltd StarAd

Sort by [Date Posted](#) results/page

8 vehicles



toyota hiace 2024

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota hiace 2024		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Hiace 3.0M (COE till 09/2024)		\$25,800	\$10,990 /yr	15-Oct-2009	2,982 cc	-	Van	Available
	Fuel Type: Diesel A very low price good condition van to start off a business. Free road tax and accessories like front camera, etc! Offer high trade in! 100...								
	ABS Bus Pte Ltd Posted: 27-May-2022								
	Toyota Hiace 3.0M (COE till 03/2024)		\$20,800	\$11,280 /yr	31-Mar-2009	2,982 cc	-	Van	Available
	Fuel Type: Diesel 2009 Toyota Hiace 5 Door, Still In Good Condition. Sell As It Is. 5 Years More Renewable. Loan Can Be Arranged.								
	Think One Automobile & Trading Posted: 27-May-2022								
	Toyota Hiace Commuter 3.0A GL (COE till 01/2024)		\$29,800	\$18,440 /yr	08-Jan-2009	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Best deal with Skylink Auto. Low Mileage and Smooth Transmission. 3 Month Warranty, Fully Serviced Before Handover + Additional 2 F...								
	Skylink Auto Pte Ltd Posted: 24-May-2022								
	Toyota Hiace 3.0M DX (COE till 04/2024)		\$22,800	\$11,820 /yr	12-Jun-2009	2,982 cc	-	Van	Available
	Fuel Type: Diesel Reliable Toyota Hiace! Rear With Checker Plate! No Repair Required! Wear & Tear Replaced Too! Tip Top Engine And Gearbox Condition...								
	Posted: 14-Apr-2022								
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota Hiace 3.0M DX (COE till 03/2024)		\$20,800	\$11,540 /yr	16-Mar-2009	2,982 cc	-	Van	Available
	Fuel Type: Diesel New Aircon Compressor, Fully Wear And Tear Parts Even Clutch And Bearing Changed, Pioneer Bluetooth And Reverse Camera, Tip-top...								
	Posted: 12-Apr-2022								
	Toyota Hiace Commuter 3.0A GL High Roof (COE till 12/2024)		\$39,800	\$15,670 /yr	10-Dec-2009	2,982 cc	-	Bus	Available

[Compare](#)

FC AUTO-GARAGE PTE LTD
 8 KAKI BUKIT AVE 4
 #04-03 PREMIER@KB
 SINGAPORE 415875
 Mobile: 90110243
 Co. Reg. No.: 202115045W

Not Authorised
 Marcus Lee
 HP90096608



5 days 27/5/22
 L/S \$4000

ESTIMATED REPAIR COST DETAILS

Take photo After repair

ACC22050007

To: SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PI
 #03-03 SINGAPORE LAND TOWER
 SINGAPORE 048623

Date: 26/05/2022
 Vehicle No.: GBB-3509-X
 Make: TOYOTA
 Model: HIACE
 Chassis No.: JTFHT02P000036010
 YoM: 2008

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR TAILGATE <i>3odgros</i>	<i>2091.00</i>	\$2,262.70	—
2	REAR TAILGATE ABSORBER L&R <i>111</i>		\$761.00	X
2	REAR TAILGATE HINGE RH & LH <i>111</i>		\$178.40	X
1	REAR TAILGATE LOGO <i>111</i>	<i>68.50</i>	\$88.60	—
1	REAR TAILGATE WEATHERSTRIP <i>7up</i>	<i>412.60</i>	\$468.00	—
1	REAR TAILGATE INNER TRIM BOARD <i>111</i>		\$315.60	X
1	REAR BUMPER <i>D.S</i>	<i>458.80</i>	\$495.80	—
1	REAR BUMPER RETAINER LH <i>one</i>		\$65.80	—
1	REAR BUMPER RETAINER RH <i>111</i>		\$65.80	X
4	REAR BUMPER LOWER BRACKET <i>3set</i>	<i>26.40 x 4 = 105.60</i>	\$191.20	?
1	END PANEL INNER <i>R</i>		\$550.00	X
1	END PANEL OUTER <i>DP</i>		\$420.60	?
1	END PANEL TOP GARNISH <i>111</i>		\$162.00	X
1	REAR CORNER GARNISH LH <i>one</i>		\$98.60	—
1	REAR CORNER GARNISH RH <i>one n/c</i>		\$98.60	X
1	SPARE TYRE BRACKET <i>111</i>		\$85.60	X
1	SPARE TYRE CARRIER <i>111</i>		\$380.60	X
1	REAR FLOOR PANEL <i>R</i>		\$1,982.50	X
1	PLATE BACK DOOR SCUFF <i>111</i>		\$94.50	X
1	TAIL LAMP (LH) <i>one n/c</i>		\$355.60	X
1	TAIL LAMP PANEL LH <i>R</i>		\$596.40	X
1	TAIL LAMP RH <i>one n/c</i>		\$355.60	X
1	TAIL LAMP PANEL RH <i>111</i>		\$596.40	X
2	EXHAUST PIPE MOUNTING <i>111</i>		\$370.80	X
1	EXHUAST MUFFLER <i>111</i>		\$1,565.20	X
1	REAR CORNER PANEL LHS <i>R</i>		\$256.80	X
1	REAR CORNER PANEL RHS <i>111</i>		\$256.80	X
<i>1set</i>	REAR BUMPER REVERSE SENSOR <i>111</i>		\$280.00	<i>200 s/n</i>
1	<i>Tailgate lock</i>	<i>shorted/Dupe</i>	<i>\$350.60</i>	✓

(252)

ESTIMATED REPAIR COST DETAILS

ACC22050007

Sub Total	\$13,237.50
Discount 25% on Parts	(\$3,309.38)
	\$9,928.13

Special Nett

1 set REAR BUMPER CLIPS	\$50.00	✓
1 TAILGATE STICKER - 70KM	\$25.00	10
1 REAR WINDSCREEN SEALANT	\$80.00	4.0
1 PANEL SEALANT	\$95.00	50
1 WINDSCREE AD STICKER - LALAMOVE	\$180.00	X
10 REAR TAILGATE INNER TRIM BOARD CLIPS	\$60.00	X
Sub Total	\$490.00	

Labour & Misc

TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	\$1,200.00	700
TO PUTTY AND RESPRAY PAINTING ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	\$1,000.00	600
SPRAY RUST PROOF ON AFFECTED AREA	\$80.00	50
TO SUPPLY UNDER COATING/PUTTY ON PARTS REPLACED	\$60.00	X
TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	\$60.00	X
DISCONNECT AND CHECK ELCTRICAL WIRING, HARNESS, WIRE SOCKET	\$60.00	20
REMOVE AND REFIT REAR WINDSCREEN	\$150.00	120
REMOVE AND REPLACE REVERSE SENSOR	\$60.00	50
DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW BOOT LID/FACILITATE REPAIR	\$120.00	60
REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	\$80.00	X
REMOVE AND REPLACE EXHAUST PIPE/SYSTEM T FACILITATE REPAIR	\$100.00	X
Sub Total	\$2,970.00	

Sub Total	\$13,388.13
GST 0%	-
Total	\$13,388.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-4072.10
 252
 3254.07
 350
 1600
 5004.07
 202
 4603.