

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN BOON TONG
68 PUNGGOL WALK
#07-38
SINGAPORE 828784

Estimate No: MC1902702
Date: 24 May 2022
Policy No: MT/00664515/02
Veh Reg No: SFV1485R
Make/Model: SUBARU FORESTER
2.0I-L CVT

ATTN:

Your Ref No: SFV1485R
Claim Type: Third Party
Accident Date: 23/05/2022
TP Veh Reg No: SLV966E

Estimate Repair Cost to Vehicle No :SFV1485R

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN MLDG TOP	1 PC	59.50	
2 TAILGATE	1 PC	1,072.40	
3 TAILGATE EMBLEM	1 PC	88.30	
4 TAILGATE SUBARU LOGO	1 PC	72.40	
5 TAILGATE FORESTER LOGO	1 PC	72.40	
6 REAR BUMPER	1 PC	540.70	
7 REAR BUMPER SIDE RETAINER LH & RH	2 PC	52.60	
8 REAR BUMPER CLIPS	15 PC	52.50	
9 REAR BUMPER TOW COVER	1 PC	14.30	
10 REAR BUMPER LOWER GARNISH COVER - CHECK PRICE	1 PC	0.0000	
11 REAR BUMPER REFLECTOR LH	1 PC	30.40	
12 REAR BUMPER REINFORCEMENT	1 PC	320.90	
13 REAR END PANEL	1 PC	320.70	
		2,697.10	
	Less 20%	539.42	2,157.68
Special Nett			
14 REVERSE SENSOR	1 SET	200.00	
15 INNER SEAL	1 PC	20.00	
16 WINDSCREEN SEALANT	1 PC	40.00	
		260.00	260.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
21 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	
22 TO SPRAY TAILGATE,REAR BUMPER,END PANEL.	1 PC	800.00	
		1,880.00	1,880.00


Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN BOON TONG
68 PUNGGOL WALK
#07-38
SINGAPORE 828784

Estimate No: MC1902702
Date: 24 May 2022
Policy No: MT/00664515/02
Veh Reg No: SFV1485R
Make/Model: SUBARU FORESTER
2.0I-L CVT

ATTN:

Your Ref No: SFV1485R
Claim Type: Third Party
Accident Date: 23/05/2022
TP Veh Reg No: SLV966E

Estimate Repair Cost to Vehicle No :SFV1485R

Description	Quantity	List Price S\$	Amount S\$
		Total	S\$ 4,297.68
		Add GST @ 7%	300.84
		Total Amount Payable	S\$ 4,598.52

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FIVE HUNDRED NINETY EIGHT AND CENTS FIFTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

Zila
Ah Lim Motor Company

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	183A

Vehicle Details

Vehicle No.:	SFV1485R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2022
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	FB20YE30679
Chassis No.:	JF1SJ5KC5JG111617
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,619.00
Original Registration Date:	20 Sep 2018
First Registration Date:	20 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$13,619.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2028
PARF Rebate Amount:	\$10,214.00

Intended COE Rebate Details

COE Expiry Date:	19 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$20,238.00
Total Rebate Amount:	\$30,452.00

The information contained herein is correct as at 23 May 2022

OK