



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004984/Kqy3m4 Date: 13/07/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBQ 5147P	Veh. Inspected	SNE 977P	
Policy No.	D21MTMC01006395	Coverage (\$)	0.00	
Claim No.	CMTD2201814/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW Z4 (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBALL32080E749874	Colour	WHITE	
Odometer	98487 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/35 ZR19	NEXEN	6 mm	
L/H Front Tyre	235/35 ZR19	NEXEN	6 mm	
R/H Rear Tyre	235/35 ZR19	NEXEN	5 mm	
L/H Rear Tyre	235/35 ZR19	NEXEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2022	Inspection Date	30/05/2022	
Survey held at	5038 ANG MO KIO IND PARK 2 #01-405 S569541			
Repairer	MASSIVE TRADING & AUTO			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	