



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III22004254/Gqy3e2-1	
			Date: 10/06/2022	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 5982P	Veh. Inspected	SLE 9357T
	Policy No.	D20MPC0007212_01	Coverage (\$)	0.00
	Claim No.	MPC2022D0002345	Excess (\$)	0.00
	Assign From	CARINE KEK	Assign Date	26/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11113905	Colour	WHITE
	Odometer	89606 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/05/2022	Inspection Date	09/05/2022
	Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES 3023A UBI ROAD 1 #01-63 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	