



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22005007/Gqy3m4 Date: 16/08/2022 Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKE 5461M
	Policy No.	SP2001407488-01	Coverage (\$)	0.00
	Claim No.	2022 22004996FR	Excess (\$)	1,100.00
	Assign From	SHANTI	Assign Date	27/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C 180	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDD2040452A679929	Colour	SILVER
	Odometer	105833 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 ZR17	MICHELIN	6 mm
	L/H Front Tyre	225/45 ZR17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 ZR17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 ZR17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/05/2022	Inspection Date	27/05/2022
	Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE MARKET VALUE IS S\$86,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	