



## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel. 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**  
CCPL

Singapore

MVA : Loke Wai Yang

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/05/2022
Vehicle Reg. No.:	SHB3111M	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	24/07/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU298670	Chassis No:	KMHC851CVKU164822
Odometer:	227380 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,540.56
Miscellaneous Items	11.00
Labour	840.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,391.56</b>
<b>+ GST 7.00% (S\$)</b>	<b>167.41</b>
<b>Nett Amount (S\$)</b>	<b>2,558.97</b>

This claim is handled by: LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 May 2022)  
**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB3111M/26/05/2022 15:05  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	*459.40 FLX <sup>FL</sup>
2	1		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <sup>FL</sup>
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	*451.25 FL <sup>FL</sup>
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FL <sup>FL</sup>
5	1		*ANTENNA SMARTKEY	20.00	0.00	*40.50 FL <sup>FL</sup>
6	1		*REAR BUMPER FOG LAMP	20.00	0.00	*201.50 FL <sup>FL</sup>
7	1		*REAR BUMPER RUBBER MAT	0.00	0.00	*50.00 FL <sup>FL</sup>
8	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	*55.00 FL <sup>FL</sup>
9	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*180.00 FL <sup>FL</sup>

F=Franchise part, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,854.45</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>313.89</b>
<b>Total Parts (S\$)</b>	<b>1,540.56</b>

ComfortDelGro Engineering Pte Ltd/SHB3111M/26/05/2022 15:05. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	350 400.00
2	SPRAY PAINTING CHARGE	New	250 300.00
3	CHECK ALL LIGHTING	New	30 60.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 80.00
<b>Gross Labour Cost (S\$)</b>			<b>840.00</b>

ComfortDelGro Engineering Pte Ltd/SHB3111M/26/05/2022 15:05. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan  
 82255969  
 2915/22 1430  
 HSP/P 20'ng SWP

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

COMFORTDELORO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 28.05.2022  
Time: 09:29:57  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTF LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305517482  
REGN NO : SHB3111M  
MILEAGE : 000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 24.07.2019  
DATE/TIME IN : 26.05.2022 13:10  
ACCIDENT DATE : 26.05.2022

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
PART REQUISITION						
0001	28-01-0104-2029-A VEHICLE NUMBER PLATE REAR	1		55.00	0.00	55.00
0002	04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1		461.25	20.00	369.00
0003	09-01-9999-0068-A REVERSE SENSOR ASSY*	1		180.00	2.00	180.00
<b>SUB-TOTAL :</b>						<b>604.00</b>

JOB NATURE

0000	L	REAR BUMPER CLIPS				17.60
0001	L	MERIMEN FEE				11.00
0002	PB	PANEL BEATING SHB3111M-TP				350.00
0003	SP	SPRAYPAINT CHARGE				250.00
0004	20-204	REMOVE/REFIX REVERSE SENSOR				30.00
0005	17-01	CHECK ALL LIGHTING				30.00
<b>SUB-TOTAL :</b>						<b>683.60</b>

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305517482  
REGN NO : SHB3111M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 24.07.2019  
DATE/TIME IN : 26.05.2022 13:1  
ACCIDENT DATE : 26.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,292.60

MVA NAME & SIGNATURE

DATE:

  
MVA Name: Wei Yang  
DATE: 28/5/22

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE: