

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KOH WEI SHENG VINCENT
BLK 187B RIVERVALE DRIVE #15-862

SINGAPORE 542187

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/05/2022
TP Veh Reg No: SLK7170X

Estimate No: MC1902697
Date: 23 May 2022
Policy No: P10342443R02
Veh Reg No: SLX8275C
Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

Estimate Repair Cost to Vehicle No :SLX8275C

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	41.00	
2 REAR BOOT LOGO ATTRAGE	1 PC	38.00	
3 REAR BOOT LOGO MIVEC TECHNOLOGY	1 PC	60.00	
4 REAR BOOT LOCK	1 PC	206.00	
5 REAR BOOT LOCK CATCH	1 PC	25.00	
6 REAR BOOT RUBBER	1 PC	150.00	
7 REAR BUMPER	1 PC	708.00	
8 REAR BUMPER SIDE RETAINER LH & RH	2 PC	52.00	
9 REAR BUMPER CLIPS	12 PC	60.00	
10 REAR END PANEL	1 PC	402.00	
11 REAR END PANEL GARNISH	1 PC	65.00	
		1,807.00	
	Less 20%	361.40	1,445.60
Special Nett			
12 BOOT LOGO CC - check price	1 PC	0.0000	
13 NUMBER PLATE (OPC)	1 PC	35.00	
14 REVERSE SENSOR SET	1 PC	200.00	
		235.00	235.00
LABOUR			
15 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00	
16 TO ARRANGE, SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY.	1 PC	60.00	
17 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
18 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	
19 TO SPRAY BOOT, REAR END PANEL, SPARE TYRE PANEL	1 PC	650.00	
		1,530.00	1,530.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : KOH WEI SHENG VINCENT
BLK 187B RIVERVALE DRIVE #15-862

SINGAPORE 542187

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/05/2022
TP Veh Reg No: SLK7170X

Estimate No: MC1902697
Date: 23 May 2022
Policy No: P10342443R02
Veh Reg No: SLX8275C
Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

Estimate Repair Cost to Vehicle No :SLX8275C

Description	Quantity	List Price S\$	Amount S\$
		Total	S\$ 3,210.60
		Add GST @ 7%	224.74
		Total Amount Payable	S\$ 3,435.34

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED THIRTY FIVE AND CENTS THIRTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE