

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 1900244032  
 Claims No. 0073132642SG  
 Sum Insured: \_\_\_\_\_ Excess: 300  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SKH 69115 Yr Regn: 15/11/19  
 Type:  M.Cap /  M.Cycle /  Bus / Van /  Lorry /  Taxi /  Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Audi A3 c.c. 999  
 Colour: Red A/C:  Insured /  Std /  NI /  NA  
 Sp. Reading: 93306 T/Radio:  Insured /  Std /  NI /  NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZZ8VYKA127470  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  Inorder /  Jammed /  Leaked /  Burnt or \_\_\_\_\_  
 Brake:  Inorder /  Jammed /  Leaked /  Burnt or \_\_\_\_\_  
 Mod:  Nil /  S/Rim /  STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/55R16  
 R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S                                 | O/S                                 |

Bal. of Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS  DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front R/Bal. 5 mm Rear R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 26/5/22 D.O.I. 30/5/22

Survey held at Premium  
 Des. of Damages:  Fnt /  Rear /  O/S /  N/S /  U/C /  Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction  |
|-------------|---|
|             | MV - IIIK   |
|             | PV - 41, 001  |
|             | NV - 69, 959  |
| 25/11/22    | Final fig \$67,682.65 confirmed by email (Red 81,596.45, 54%) |

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: 24  
 Resurvey No. of Trip: 1

1) Date/Time, File Return to?  
 2) 15/12/22-typist

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_

|                 |  |
|-----------------|--|
| Survey Fee:     |  |
| Transportation: |  |
| \$ + RS. \$     |  |
| Photos          |  |
| Others          |  |
| TOTAL           |  |

Report Format: Merimen  
 Lump Sum / L.S.: (\$ 67,682.65)

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0435/2022/JT  
DATE : 27-May-22  
WIP : 25721

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/5/2022.

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HO WEI RUI, GILBERT  
ADDRESS : 501 DUNMAN ROAD  
#11-03  
SINGAPORE 439193  
TELEPHONE : HP +65 9669 8629  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900244032-01  
VEHICLE NO : SKH 6911 J  
MODEL CODE : AUDI A3 SB 1.0 TFSI  
MODEL YEAR : 15/11/2019  
ENGINE NO : CHZ C33218  
CHASSIS NO : WAUZZZ8VXKA121470  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 26-May-22  
PLACE OF ACCIDENT : STADIUM WALK



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

| S/N                             | NATURE OF JOBS   | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|---------------------------------|--|----------------------|----------------------------|
| 1                               | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.                                     | S/N \$ 360.00 /      |                            |
| 2                               | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. <sup>2 x 250</sup>  | S/N \$ 700.00        | ? 500                      |
| 3                               | TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS. | S/N \$ 1,400.00 /    |                            |
| 4                               | TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.   | S/N \$ 800.00        | ? (phd)                    |
| 5                               | TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR. <sup>RH</sup>  | S/N \$ 560.00        | 280                        |
| 6                               | TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES.  | S/N \$ 2,800.00      | ? (phd)                    |
| <b>SUB-TOTAL LABOUR CHARGES</b> |  | <b>: \$ 6,620.00</b> |                            |



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

| S/N                             | NATURE OF JOBS   |          | ESTIMATED CHARGES  | SURVEYOR'S RECOMMENDATIONS |
|---------------------------------|--|----------|--------------------|----------------------------|
| 7                               | TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY. | S/N \$   | 2,400.00           | ? (phn)                    |
| 8                               | TO SETUP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.  | S/N \$   | 2,400.00           | ? (phn)                    |
| 9                               | TO REMOVE AND RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS.   | S/N \$   | 980.00             | ? X                        |
| 10                              | TO RENEW FRONT WINDSCREEN.   | S/N \$   | 480.00             | /                          |
| 11                              | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.  | S/N \$   | 400.00             | X                          |
| 12                              | TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.  | S/N \$   | 200.00             | 150                        |
| <b>SUB-TOTAL LABOUR CHARGES</b> |  | <b>:</b> | <b>\$ 6,860.00</b> |                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

| S/N                         | NATURE OF JOBS   | ESTIMATED CHARGES               | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|---------------------------------|----------------------------|
| 13                          | TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND LHS FRONT CHASSIS FRAME WITH COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | S 14,000.00<br><i>6.5 x 500</i> | 3250                       |
| 14                          | TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT FENDER TOP SUPPORTS, LHS FRONT CHASSIS FRAME WITH COVER PLATE, BOTH FRONT DOORS AND BOTH UPP A-PILLARS.  | S 8,500.00<br><i>550 x 6</i>    | 3300                       |
| 15                          | TO CARRY OUT PRE/POST WHEEL ALIGNMENT.   | S/N S 480.00                    | ?                          |
| 16                          | TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.   | S/N S 280.00                    | X                          |
| 17                          | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.  | S/N S 384.00                    | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |  | <b>S 37,124.00</b>              |                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

|                              |  |     | DAMAGED PARTS & PRICES |                    |
|------------------------------|--|-----|------------------------|--------------------|
| S/N                          | PARTS DESCRIPTION                                | QTY | S/NETT                 | REMARKS            |
| 1                            | FRONT BUMPER / BR                                | 1   | \$                     | 2,146.00           |
| 2                            | FRONT BUMPER FIXING PARTS - MC                   | 1   | \$                     | 195.00             |
| 3                            | FRONT BUMPER GUIDE SECTION- LH / RH / BT         | 2   | \$                     | 86.00              |
| 4                            | FRONT BUMPER GRILLE - CENTER / BR                | 1   | \$                     | 179.00             |
| 5                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER / BR | 1   | \$                     | 332.00             |
| 6                            | FRONT BUMPER CLOSING ELEMENT - LH / RH / BR      | 2   | \$                     | 636.00             |
| 7                            | RADIATOR GRILLE / BR                             | 1   | \$                     | 1,578.00           |
| 8                            | RADIATOR GRILLE CLOSING ELEMENT / BR             | 1   | \$                     | 210.00             |
| 9                            | AIR COND STICKER - MC                            | 1   | \$                     | 9.00               |
| 10                           | CAUTION STICKER - MC                             | 1   | \$                     | 16.00              |
| 11                           | FRONT BUMPER AIR GUIDE GRILLE - LH / RH / BR     | 2   | \$                     | 420.00             |
| 12                           | FRONT BUMPER FOAM FILLER PIECE / BR              | 1   | \$                     | 211.00             |
| 13                           | FRONT BUMPER REINFORCEMENT BEAM COVER / BR       | 1   | \$                     | 136.00             |
| 14                           | FRONT BUMPER REINFORCEMENT BEAM / OK             | 1   | \$                     | 847.00             |
| 15                           | HORN - LH / RH / BR                              | 2   | \$                     | 426.00             |
| 16                           | FRONT FENDER - LH / RH / BT                      | 2   | \$                     | 1,908.00           |
| 17                           | FRONT FENDER ATTACHMENT PARTS X                  | 1   | \$                     | 75.00              |
| 18                           | FRONT FENDER BRACKET - LH / RH / BT              | 2   | \$                     | 112.00             |
| 19                           | FRONT FENDER POP RIVET / MC                      | 16  | \$                     | 61.00              |
| 20                           | FRONT FENDER CLOSING ELEMENT - LH / RH / MC      | 2   | \$                     | 136.00             |
| <b>SUB TOTAL SPARE PARTS</b> |  |     | :                      | <b>\$ 9,719.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

|                              |  |     | DAMAGED PARTS & PRICES |                 |
|------------------------------|--|-----|------------------------|-----------------|
| S/N                          | PARTS DESCRIPTION                              | QTY | S/NETT                 | REMARKS         |
| 21                           | FRONT FENDER BRACE - LH / RH ?                 | 2   | \$                     | 214.00          |
| 22                           | FRONT FENDER BRACKET END - LH / RH - nrc       | 2   | \$                     | 62.00           |
| 23                           | FRONT FENDER INSULATION - LH / RH ?            | 2   | \$                     | 96.00           |
| 24                           | FRONT FENDER CLOSING ELEMENT END - LH / RH ?   | 2   | \$                     | 74.00           |
| 25                           | FRONT WHEEL HOUSING LINER - LH / RH - CR4      | 2   | \$                     | 366.00          |
| 26                           | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - m | 1   | \$                     | 60.00           |
| 27                           | BONNET - m                                     | 1   | \$                     | 3,370.00        |
| 28                           | BONNET ATTACHMENT PARTS ?                      | 1   | \$                     | 172.00          |
| 29                           | BONNET HINGE - LH / RH - BT                    | 2   | \$                     | 136.00          |
| 30                           | BONNET SIDE COVER - LH / RH - CR4              | 2   | \$                     | 92.00           |
| 31                           | BONNET ABSORBER X                              | 1   | \$                     | 110.00          |
| 32                           | BONNET EDGE PROTECTION - m                     | 1   | \$                     | 31.00           |
| 33                           | BONNET CATCH HOOK - UPPER - BT                 | 1   | \$                     | 100.00          |
| 34                           | BONNET STRIKER - LH / RH - BT                  | 2   | \$                     | 246.00          |
| 35                           | BONNET CATCH HOOK - LOWER - BT                 | 1   | \$                     | 71.00           |
| 36                           | BONNET LOCK MICRO-SWITCH - BT                  | 2   | \$                     | 455.00          |
| 37                           | BONNET LOCK COVER m ?                          | 2   | \$                     | 8.00            |
| 38                           | BONNET BOWDEN CABLE - CENTER ?                 | 1   | \$                     | 64.00           |
| 39                           | BONNET RELEASE CABLE COVER ?                   | 1   | \$                     | 11.00           |
| 40                           | BONNET LOCK CABLE ?                            | 1   | \$                     | 82.00           |
| <b>SUB TOTAL SPARE PARTS</b> |  |     | <b>\$</b>              | <b>5,820.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

|                              |  |     | DAMAGED PARTS & PRICES |                  |
|------------------------------|--|-----|------------------------|------------------|
| S/N                          | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS          |
| 41                           | BONNET SOUND ABSORBER ✓                    | 1   | \$                     | 244.00           |
| 42                           | BONNET PLENUM CHAMBER - ✓ CUT              | 1   | \$                     | 199.00           |
| 43                           | HEADLIGHT - LH / RH - ✓ BR                 | (2) | \$                     | 11,758.00        |
| 44                           | HEADLIGHT POWER MODULE - LH / RH ?         | 2   | \$                     | 1,700.00         |
| 45                           | HEADLIGHT CONTROL UNIT ?                   | 2   | \$                     | 1,249.00         |
| 46                           | LED HEAT SINK - LH / RH ?                  | 2   | \$                     | 1,636.00         |
| 47                           | HEADLIGHT HOSE - LH / RH ?                 | 2   | \$                     | 92.00            |
| 48                           | LIFT CYLINDER (LH) / RH - ✓ MIS            | 2/1 | \$                     | 312.00           |
| 49                           | LIFT CYLINDER HOSE - ✓ TH                  | 1   | \$                     | 78.00            |
| 50                           | LIFT CYLINDER PUMP - ✓ BR                  | 1   | \$                     | 171.00           |
| 51                           | WINDSCREEN WASHER SYSTEM PUMP ✓            | 1   | \$                     | 137.00           |
| 52                           | WASH WATER RESERVOIR - ✓ CR4               | 1   | \$                     | 225.00           |
| 53                           | WINDSCREEN STRAINER ✓                      | 1   | \$                     | 24.00            |
| 54                           | WINDSCREEN STRINER END CAP ✓               | 1   | \$                     | 24.00            |
| 55                           | WINDSCREEN SPRAY NOZZLE HEATED - LH / RH ? | 2   | \$                     | 234.00           |
| 56                           | LOCK CARRIER - ✓ BR                        | 1   | \$                     | 806.00           |
| 57                           | A/C CONDENSER - ✓ BR                       | 1   | \$                     | 569.00           |
| 58                           | REFRIGERANT LINE ?                         | 1   | \$                     | 621.00           |
| 59                           | REFRIGERANT LINE ?                         | 1   | \$                     | 499.00           |
| 60                           | REFRIGERANT LINE ?                         | 1   | \$                     | 569.00           |
| <b>SUB TOTAL SPARE PARTS</b> |  | :   | \$                     | <b>21,147.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

|                              |   |     | DAMAGED PARTS & PRICES |         |
|------------------------------|---|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                             | QTY | S/NETT                 | REMARKS |
| 61                           | REFRIGERANT LINE BRACKET ?                    | 1   | \$ 29.00               |         |
| 62                           | OUTSIDE TEMPERATURE SENSOR BRACKET / nec      | 1   | \$ 21.00               |         |
| 63                           | EXTERNAL TEMPERATURE SENSOR ?                 | 1   | \$ 64.00               |         |
| 64                           | ADDITIONAL RADIATOR / OO (photo)              | 1   | \$ 959.00              |         |
| 65                           | RADIATOR BRACKET - UPPER / BR                 | 2   | \$ 90.00               |         |
| 66                           | RADIATOR BUSH - LOWER / nec                   | 2   | \$ 22.00               |         |
| 67                           | RADIATOR / OO (photo)                         | 1   | \$ 1,061.00            |         |
| 68                           | RADIATOR FAN RING / BR (photo)                | 1   | \$ 1,488.00            |         |
| 69                           | RADIATOR AIR GUIDE - LH / RH ?                | 2   | \$ 56.00               |         |
| 70                           | RADIATOR SEAL - RH OUTER X                    | 1   | \$ 9.00                |         |
| 71                           | RADIATOR AIR GUIDE - UPPER CENTER ?           | 1   | \$ 14.00               |         |
| 72                           | RADIATOR COOLANT / nec                        | 6   | \$ 282.00              |         |
| 73                           | QUICK RELEASE COUPLING COOLANT HOSE - FRONT ? | 1   | \$ 251.00              |         |
| 74                           | QUICK RELEASE COUPLING COOLANT HOSE - UPPER ? | 1   | \$ 125.00              |         |
| 75                           | COOLANT PIPE - UPPER ?                        | 1   | \$ 65.00               |         |
| 76                           | COOLANT PIPE - LOWER ?                        | 1   | \$ 34.00               |         |
| 77                           | QUICK RELEASE COUPLING COOLANT HOSE - LOWER ? | 1   | \$ 60.00               |         |
| 78                           | QUICK RELEASE COOLANT HOSE ?                  | 1   | \$ 159.00              |         |
| 79                           | INTAKE AIR DUCT COVER ?                       | 1   | \$ 30.00               |         |
| 80                           | INTAKE AIR GUIDE - LOWER ? / BR               | 1   | \$ 59.00               |         |
| <b>SUB TOTAL SPARE PARTS</b> |   |     | <b>\$ 4,878.00</b>     |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

| S/N                          | PARTS DESCRIPTION                      | QTY | DAMAGED PARTS & PRICES |                 |
|------------------------------|--|-----|------------------------|-----------------|
|                              |  |     | S/NETT                 | REMARKS         |
| 81                           | INTAKE AIR GUIDE - UPPER ?             | 1   | \$                     | 21.00           |
| 82                           | WATER DRAINAGE HOSE ?                  | 1   | \$                     | 37.00           |
| 83                           | INTAKE AIR GUIDE - LOWER ?             | 1   | \$                     | 69.00           |
| 84                           | AIR FILTER BOX ?                       | 1   | \$                     | 310.00          |
| 85                           | INTAKE MANIFOLD - UPPER ?              | 1   | \$                     | 156.00          |
| 86                           | INTAKE MANIFOLD - LOWER ?              | 1   | \$                     | 786.00          |
| 87                           | THROTTLE BODY ?                        | 1   | \$                     | 796.00          |
| 88                           | CHARGE AIR COOLER ?                    | 1   | \$                     | 864.00          |
| 89                           | TOOTHED BELT GUARD - UPPER / LOWER ?   | 2   | \$                     | 160.00          |
| 90                           | TOOTHED BELT GUARD ?                   | 1   | \$                     | 202.00          |
| 91                           | POLY V-BELT ?                          | 1   | \$                     | 52.00           |
| 92                           | BATTERY CONSOLE ?                      | 1   | \$                     | 203.00          |
| 93                           | BATTERY HEAT INSULATION ?              | 1   | \$                     | 96.00           |
| 94                           | BATTERY FILLED CHARGED ?               | 1   | \$                     | 584.00          |
| 95                           | BATTERY PROTECTION COVER ?             | 1   | \$                     | 145.00          |
| 96                           | BATTERY MONITORING CONTROL UNIT ?      | 1   | \$                     | 568.00          |
| 97                           | FRONT FENDER TOP SUPPORT - LH / RH ?   | 2   | \$                     | 164.00          |
| 98                           | FRONT CHASSIS FRAME COVER PLATE - LH ? | 1   | \$                     | 107.00          |
| 99                           | SIDE MEMBER - LH ?                     | 1   | \$                     | 742.00          |
| 100                          | GEARBOX MOUNTING BRACKET - LH ?        | 1   | \$                     | 123.00          |
| <b>SUB TOTAL SPARE PARTS</b> |  | :   | <b>\$</b>              | <b>6,185.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

| S/N                          | PARTS DESCRIPTION                                   | QTY | DAMAGED PARTS & PRICES |                  | REMARKS |
|------------------------------|---|-----|------------------------|------------------|---------|
|                              |   |     | S/NETT                 |                  |         |
| 101                          | NOISE INSULATION ?                                  | 1   | \$                     | 376.00           |         |
| 102                          | BASE ENGINE ?                                       | 1   | \$                     | 18,936.00        |         |
| 103                          | SUSPENSION SUBFRAME ASSEMBLY CARRIER ?              | 1   | \$                     | 1,105.00         |         |
| 104                          | BONDED RUBBER BUSHES ?                              | 1   | \$                     | 116.00           |         |
| 105                          | GEARBOX MOUNTING - LH ?                             | 1   | \$                     | 286.00           |         |
| 106                          | ENGINE MOUNTING - RH ?                              | 1   | \$                     | 277.00           |         |
| 107                          | ENGINE MOUNTING CONSOLE - LH ?                      | 1   | \$                     | 209.00           |         |
| 108                          | ENGINE SUPPORT ?                                    | 1   | \$                     | 243.00           |         |
| 109                          | ENGINE SUPPORT - LH / RH OUTER ?                    | 2   | \$                     | 50.00            |         |
| 110                          | PENDULUM SUPPORT ?                                  | 1   | \$                     | 100.00           |         |
| 111                          | FRONT WINDSCREEN COLOUR STRIP - Bl                  | 1   | \$                     | 1,206.00         |         |
| 112                          | RAIN SENSOR GEL FOIL - ne                           | 1   | \$                     | 130.00           |         |
| 113                          | SPRING CLIP x                                       | 1   | \$                     | 23.00            |         |
| 114                          | PRIMER - ne   | 1   | \$                     | 22.00            |         |
| 115                          | WINDSCREEN WATER DEFLECTOR STRIP (LH) / RH - (LH) x | 2   | \$                     | 150.00           |         |
| 116                          | AERO WIPER ARM - LH / RH x                          | 2   | \$                     | 230.00           |         |
| 117                          | AERODYNAMIC WIPER BLADE x                           | 1   | \$                     | 101.00           |         |
| 118                          | AERODYNAMIC WIPER BLADE CAP x                       | 2   | \$                     | 20.00            |         |
| 119                          | FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH x  | 2   | \$                     | 604.00           |         |
| 120                          | ROOF CHROME MOLDING - LH / RH x                     | 2   | \$                     | 1,330.00         |         |
| <b>SUB TOTAL SPARE PARTS</b> |   |     | <b>\$</b>              | <b>25,514.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

| S/N                         | PARTS DESCRIPTION             | QTY | DAMAGED PARTS & PRICES |                   |  |
|-----------------------------|-------------------------------|-----|------------------------|-------------------|--|
|                             |                               |     | S/NETT                 | REMARKS           |  |
| 121                         | GEARBOX ?                     | 1   | \$                     | 18,564.00         |  |
| 122                         | TRANSMISSION FLUID ?          | 5   | \$                     | 353.00            |  |
| 123                         | ELECTRIC SYSTEM HOUSING ?     | 1   | \$                     | 93.00             |  |
| 124                         | FUSE BOX COVER ?              | 1   | \$                     | 54.00             |  |
| 125                         | ENGINE COMPARTMENT ?          | 1   | \$                     | 27.00             |  |
| 126                         | E BOX ?                       | 1   | \$                     | 394.00            |  |
| 127                         | FRONT NO PLATE / MIS          | S/N | \$                     | 60.00             |  |
| 128                         | FRONT WINDSCREEN SEALANT / nc | S/N | \$                     | 200.00            |  |
| 129                         | ARYLIC SEALANT ?              | S/N | \$                     | 180.00            |  |
| 130                         | CAVITY WAX ?                  | S/N | \$                     | 140.00            |  |
| 131                         | METAL PILLER POWDER ?         | S/N | \$                     | 280.00            |  |
| 132                         | STONE CHIP ?                  | S/N | \$                     | 180.00            |  |
| 133                         | SUNDRIES ?                    |     | \$                     | 800.00            |  |
| <b>TOTAL SPARE PARTS</b>    |                               | :   | \$                     | <b>94,588.00</b>  |  |
| <b>TOTAL LABOUR CHARGES</b> |                               | :   | \$                     | <b>37,124.00</b>  |  |
| <b>GRAND TOTAL</b>          |                               | :   | \$                     | <b>131,712.00</b> |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Steve (LKK)  
30/5/22, 3.00pm

DD- M L  
Extra - ?  
PIP  
M BL y  
12 LPS

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 26/05/2022 12:02 (SGT)  
Date of Accident ..... 26/05/2022 08:45 (SGT)  
Exact Location of Accident ..... 3 Stadium Walk, Singapore 397692  
Additional Location Information ..... STADIUM WALK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKH6911J

INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... HO WEI RUI, GILBERT  
NRIC No ..... SXXXX230H  
Email Address ..... GILBERTHO@YMAIL.COM  
Mobile Phone No ..... (Phone) +65-96698629  
Alternative Phone No ..... +65-96698629

## VEHICLE PARTICULARS

Manufacturer ..... Audi  
Model ..... A3  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 999

## INSURANCE COMPANY

Name of Insurance Company ..... AIG Asia Pacific Insurance Pte. Ltd.  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 1900244032-01  
Cover Note Number ..... -

## DRIVER

Name of Driver ..... CHNG YING YING  
NRIC No ..... SXXXX295J

Date Of Birth  
 Occupation  
 Date Of Driving Pass  
 Driving experience  
 Gender  
 Mobile Number  
 Alt. Phone Number  
 Email Address  
 Address  
 Address complement  
 Postcode  
 Is the driver the policyholder?  
 If No, Relationship of the Driver with the Insured  
 Does Driver Own Other Vehicles?  
 Vehicle Registration Number of Other Vehicle Owned by Driver  
 Insurance Company of Other Vehicle Owned by Driver

08/05/1984  
 Indoor  
 09/12/2002  
 19 YEARS AND 5 MONTHS  
 Female  
 (Phone) +65-98333673  
 -  
 GILBERTH@YMAIL.COM  
 501 DUNMAN ROAD  
 #11-03  
 439193  
 No  
 Spouse  
 No  
 -  
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
 Weather Conditions  
 Road Surface

Collision - Major/Minor  
 Clear  
 Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
 Number of vehicles involved in the accident  
 Was anybody injured in the accident?  
 Was any injured conveyed to hospital by ambulance?  
 Was any other vehicle or property damaged?  
 Number of Passengers (Including Driver)  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No  
 2  
 No  
 -  
 Yes  
 2  
 No

PASSENGER 1

Name  
 Gender

SUSU HLAING  
 Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?  
 Was notice of intended Prosecution given?  
 If yes, against whom?

No  
 No  
 -

CIRCUMSTANCES OF ACCIDENT

SKH 6911 J EXITED SG SPORTS HUB CAR PARK L FROM THE RIGHT CAR PARK EXIT WENT STRAIGHT TO CROSS OVER TO STADIUM WALK. UPON CHECKING FOR CLEARANCE AND STADIUM WALK, PROCEEDED TO PACE FORWARD, BMW (SJM 2148 E) COME FROM STADIUM WALK. MY AUDI (SKH 6911 J) HIT ON TO THE DRIVER SIDE OF THE BMW AS WASN'T ABLE TO BRAKE IN TIME UPON SIGHTING THE BMW.

ATTACHMENT(S)

Are accident photos available for attachment?  
 Was there any video captured by Car Camera?  
 Was there any audio recorded?

Yes  
 Yes  
 No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
 Vehicle Manufacturer  
 Vehicle Model

SJM2148E  
 BMW  
 -

Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
Blue  
Private car  
ABHISH CHANDHOK  
(Phone) +65-91396687  
-  
-  
-  
-  
-  
-  
1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*Anuragi* 26 May 22 10am  
 Policyholder's Signature / Date & Time

*[Signature]* 26 May 2022 10am  
 Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel: *Tony Fung*



**Describe Circumstances of the Accident**

SKH169115 exited SG Sports Hub Carpark 1 from the right carpark exit which for vehicles to go straight to cross over to Stadium Walk. Upon checking for clearance of crossing for Stadium (ess side and Stadium Walk) proceeded to ~~the~~ pace forward. BMW (5JM2148 E) came from the adjacent part of lane at Stadium Walk. My Audi (SKH169115) hit on to the driver side of the BMW as wasn't able to brake in time upon sighting the BMW.

Lined area for additional details or notes.

**Declaration**

We declare the foregoing particulars are true in every respect

[Signature] 26 May 2010 3:20am  
Policyholder's Signature / Date & Time

[Signature] 26 May 2010 3:30am  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel Tray Fong