

## Request for Mechanical Inspection Report

Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>

Mon 30/5/2022 10:22 AM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Siti Haira BATRA (SPF)

<Siti\_Haira\_BATRA@spf.gov.sg>; Nadya MOIDEEN (SPF) <Nadya\_MOIDEEN@SPF.GOV.SG>; Wei Li GOH (SPF)

<GOH\_Wei\_Li@spf.gov.sg>; Guang Hui LEE (SPF) <LEE\_Guang\_Hui@spf.gov.sg>; SPF-TP FAIT <SPF-

TP\_FAIT@spf.gov.sg>; Syed Shameer SHAH (SPF) <Syed\_Shameer\_Shah@spf.gov.sg>; Saravanan Baba

SIVAPERUMAL (SPF) <Saravanan\_Baba\_SIVAPERUMAL@spf.gov.sg>; Richard POR (SPF)

<Richard\_Por@spf.gov.sg>

Dear Sirs,

### cc:

IO Nadya, IO Wei Li, IO Ken & FAIT SIOs, as requested by you

Mr Bryan & OC FAIT (Covering), for your information please

Mr Shameer, Mr Baba and Mr Richard, kindly assist on the POs. Amount for the following request has been approved by Dy CTP. Thank you.

May I seek your assistance to perform a detailed mechanical inspection of the following **22 cases** in the table. The ones marked in **red** are deemed to be **urgent**.

SN	IP No.	Brief Facts	Vehicles to be inspected:	IO In-Charge:
1	TP/IP/08690/2022	On 18 April 2022 sometime before 6.58 p.m., the Deceased was riding her motorcycle along PIE(ECP) at the slip road into ECP(MCE) when she lost control of her motorcycle while negotiating the left bend at the said location. Deceased was conveyed to CGH and was pronounced dead at 8.03pm at by attending Doctor. To check motorcycle for any possible mechanical failure that may have caused or contributed to the accident. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>FBG5379P</b> - Rider (Deceased)	Kamaliah
2 - 3	TP/IP/08689/2022	On 16 April 2022 sometime before 5.00 p.m., the Deceased was believed to be cycling his bicycle across the zebra crossing along Jalan Eunos at the slip road into PIE(TUAS) when he was hit by Involved Party lorry, which was proceeding across the zebra crossing from his right to left. Cyclist was conveyed to CGH and pronounced dead on the same day with multiple injuries at 6.49 p.m. To check Bicycle and Lorry for any possible mechanical issues that may cause or contribute to the accident. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>GBD1527X</b> - Driver (Potential Defendant) <b>Bicycle</b> - Pedal Cyclist (Deceased)	Kamaliah

4	TP/IP/08722/2022	On 17 April 2022 sometime before 3.45 p.m., SMN5163C skidded involving government property along Tampines Avenue 7 towards Loyang Avenue, near L/P 37. Investigation revealed that the driver was travelling straight on lane 1 of 2-lanes road at said location when suddenly there was a noise coming from the car and the steering wheel turned to the right on its own, causing the vehicle to mount the center divider and colliding into the center guard railings. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>SMN5163C</b> - Driver (Potential Defendant)	Nadya
5	TP/IP/08470/2022	On the 13 April 2022 (Wednesday) sometime around 11.43 p.m., the driver was driving the said motor taxi inside the SPC Petrol Station along Bukit Batok Street 24 and was exiting when his taxi suddenly surged forward at a fast speed. Driver informed that he only stepped gently and did not jammed the accelerator. Driver mentioned that the taxi surged forward at a high speed and he was unable to stop in time, which eventually he collided into the bushes and engine stalled. General inspection is required to inspect if there is/are any mechanical faults to the motor taxi which caused the sudden surge, to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>SH9985G</b> - Driver (Potential Defendant)	Goh Wei Li
6	TP/IP/10439/2022	On 29 April 2022 sometime before 4.50 p.m., the Deceased was riding his motorcycle along PIE(TUAS) near 36KM when he collided onto the stationary motorcar and motorcycle which was stationary on lane 1, assisting out in another RTA which occurred prior before. Deceased was conveyed to NTFGH and was pronounced dead at 2.29am the following day at by attending Doctor. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>JSB5481</b> - Rider (Deceased)	Adrian Lim
7	TP/IP/08886/2022	On the 18 April 2022 (Monday) sometime around 3.21 p.m., the driver was exiting out from the parking gantry and claimed that vehicle surged forward and collided onto a tree. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>SJV2927D</b> - Driver (Potential Defendant)	Ken Lee
8 - 9	TP/IP/08326/2022	On 15/04/2022 (Friday) sometime around	<b>FBH6542Y</b> -	Mariah

		5.56 p.m., the deceased was riding along Lim Chu Kang Road when he collided onto a motor lorry (YN7543J) who was coming out Muslim Cemetery Path 17, from the deceased's left. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	Rider (Deceased)  <b>YN7543J</b> - Driver (Potential Defendant)	
10	TP/IP/12238/2022	On 20 May 2022 sometime before 9.14 a.m., the Involved Party was driving his Garbage Truck along Anamalai Avenue on the single lane two way road when he collided onto the Deceased who was walking across the road from his left to right, causing the Deceased to fall onto the road and the Deceased's to be ran over by the Involved Party truck. Deceased sustained multiple injuries and was conveyed to NUH by the ambulance. Deceased was pronounced dead at CGH at 10.39am on the same day. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>XE6383U</b> - Driver (Potential Defendant)	Adrian Lim
11	TP/IP/03871/2022	On 18 February 2022 sometime before 12.25 p.m., the Deceased was riding his motorcycle along TPE(SLE) near 14.7KM when he collided onto the rear of another Trailer which was travelling ahead and fell onto the road. Deceased was pronounced dead at 12.51pm at scene by attending paramedics. To check motorcycle for any possible mechanical failure that may have caused or contributed to the accident. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>FBQ8087J</b> - Rider (Deceased)	Adrian Lim
12 - 13	TP/IP/09555/2022	On 22 April 2022 at about 5.13 p.m., the Involved Party was driving lorry YM9628R when the Deceased, who was riding motorcycle JSP2711 had collided into the rear right portion of lorry YM9628R. The deceased sustained multiple injuries and was treated at the hospital. He subsequently succumbed to his injuries and was pronounced dead at the hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>YM9628R</b> - Driver (Involved Party)  <b>JSP2711</b> - Rider (Deceased)	Raziz
14	TP/IP/10567/2022	On 3 May 2022 at about 5.18 p.m. the driver of the bus was making a right turn at the junction of Choa Chu Kang road into Upper Bukit Timah when he collided onto a pedestrian crossing at the pedestrian crossing. As a result the pedestrian was	<b>SG6122E</b> - Driver (Potential Defendant)	Yazid

		sent to NUH unconscious and succumbed to his injuries in hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.		
15 - 16	TP/IP/08448/2022	On 13 April 2022 at about 7.22 a.m., the rider of said motorcycle FBH 7625 K was travelling along Upper Thomson Road and had braked when motorcar SLJ 8418 G tried to avoid the motorcycle by swerving however side swiped onto the motorcycle. As a result of the accident the motorcyclist was sent to TTSB where he succumbed to his injuries. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>FBH7625K</b> - Rider (Deceased)  <b>SLJ8418G</b> - Driver (Potential Defendant)	Yazid
17	TP/IP/10841/2022	On 5 May 2022 at about 11.53 p.m. the rider of the motorcycle was travelling on lane 3 of 4 lanes when the motorcycle collided onto a stationary lorry on lane 3 of 4 lanes.. As a result the rider of the motorcycle was sent to NUH unconscious and succumbed to his injuries in hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>FBT1240M</b> - Rider (Deceased)	Yazid
18 - 19	TP/IP/11672/2022	On 13/05/2022 at about 2307hrs, the deceased was cycling on his PAB along Serangoon Road towards Upp Serangoon Road when a motorcycle, FMB4518E collided onto the deceased's PAB. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>PAB</b> - Pedal Cyclist (Deceased)  <b>FBM4518E</b> - Rider (Potential Defendant)	Mariah
20	G/20220304/0059	On 04 March 2022 at about 8.55 a.m., the driver was reversing his motorcar at the entrance of a preschool along Upper Changi Road East when a pedestrian walked towards his vehicle and had a fall. There is no evidence indicating if there was any contact between the motorcar and the said pedestrian. No other vehicles were involved in the said collision. The pedestrian subsequently succumbed to his injuries and was pronounced dead at CGH on 10/03/2022 at 6.36 p.m. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	<b>SFF319D</b> - Driver (Potential Defendant)	Firdaus
21 - 22	TP/IP/09095/2022	On 20 April 2022 sometime before 2.02 a.m., the Deceased was riding alone on his motorcycle and was travelling straight along Tampines Expressway towards Pan	<b>FBJ6994R</b> - Rider (Deceased)	Kamaliah

	<p>Island Expressway on lane 3 of the 3-lane road when he was hit by the Accused's motorcar from the rear. As a result of the accident, the Deceased fell off from his motorcycle and landed on the road. The Deceased sustained multiple injuries and was conveyed to Sengkang General Hospital. He was reported to be unconscious and pulseless. On the same day at 3.04 a.m., the Deceased succumbed to his injuries and was pronounced dead by Dr Chinmaya Shrikant Joshi at Accident &amp; Emergency Department. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.</p>	<p><b>SLE6014C -</b> Driver (Potential Defendant)</p>	
--	---	---	--

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team

Traffic Police Department | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352



**Singapore Police Force** **W** [police.gov.sg](https://police.gov.sg) **FB** [fb.com/singaporepoliceforce](https://fb.com/singaporepoliceforce) **IG** [instagram.com/singaporepoliceforce](https://instagram.com/singaporepoliceforce)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act 1935. Please notify the sender immediately if you receive this in error.