



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005101/Uty3n2 Date: 07/06/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNE 349C	Veh. Inspected	SMF 6003S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2201843/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	30/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA GLS (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHD841CMJU767443	Colour	GREY	
Odometer	109934 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HABILEAD	6 mm	
L/H Front Tyre	205/55 R16	HABILEAD	6 mm	
R/H Rear Tyre	205/55 R16	HABILEAD	6 mm	
L/H Rear Tyre	205/55 R16	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/05/2022	Inspection Date	30/05/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	