

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                 |                       |  |
|---|--|--|-----------------|-----------------------|--|
|   | GREAT AMERICA  | N INSURANCE COMPANY                    | Ref:            | CS/GAI22005105/Avy3e2 |  |
|   | 3 TEMASEK AVEN<br>#16-01 CENTENNI<br>SINGAPORE 0391  | AL TOWER                               | Date:           | 02/11/2022            |  |
|   |  |  | Code:           | GAI                   |  |
| 1.  | 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                 |                       |  |
|   | Insured Veh.   | SJJ 8238H                              | Veh. Inspected  | SJM 5909J             |  |
|   | Policy No.   |  | Coverage (\$)   | 0.00                  |  |
|   | Claim No.  | CLMOMVP000001213                       | Excess (\$)     | 0.00                  |  |
|   | Assign From  | SHERY WONG                             | Assign Date     | 30/05/2022            |  |
| 2. Vehicle Particulars & Condition                                |  |  |                 |                       |  |
|   | Make & Model   | HONDA FREED                            | C.C             | 1496                  |  |
|   | Engine No.   | HIDDEN                                 | Year of Reg.    | 2018                  |  |
|   | Chassis No.  | GB71064063                             | Colour          | BLUE                  |  |
|   | Odometer   | 64416 KM                               | Steering        | IN ORDER              |  |
|   | Brakes   | IN ORDER                               | Modification    | SPORTS RIM            |  |
|   | General  | GOOD                                   |                 |                       |  |
| 3. Conditions of Tyres  |  |  |                 |                       |  |
|   |  | Size                                   | Make            | Balance               |  |
|   | R/H Front Tyre   | 185/65 R15                             | BRIDGESTONE     | 6 mm                  |  |
|   | L/H Front Tyre   | 185/65 R15                             | BRIDGESTONE     | 6 mm                  |  |
|   | R/H Rear Tyre  | 185/65 R15                             | BRIDGESTONE     | 6 mm                  |  |
|   | L/H Rear Tyre  | 185/65 R15                             | BRIDGESTONE     | 6 mm                  |  |
| 4.  | Description of Damages   |  |                 |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.   |  |                 |                       |  |
|   | DAMAGES SEE DETAILS.   |  |                 |                       |  |
| 5.  | General Information  |  |                 |                       |  |
|   | Accident Date  | 28/05/2022                             | Inspection Date | 03/06/2022            |  |
|   | Survey held at   | y held at JACK CARS ENTERPRISE PTE LTD |                 |                       |  |
|   | BLK 3007 UBI ROAD 1 #01-450<br>SINGPORE 408700   |  |                 |                       |  |
| 5a.   | Remarks  |  |                 |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                       |  |
| 5b.   | Estimate Days of Repair  |  |                 |                       |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days   |  |                 |                       |  |
|   | <del>-</del>   |  | ,               |                       |  |