

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.29645 Date: 06<sup>th</sup> Jun 2022

Our Ref: CS3/ASM22002678/Evy3e2-1

## M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## **EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBS 5428T**

INSURED VEHICLE: SNB 1022D ACCIDENT DATE: 05/03/2022

We thank you for your instruction on 25/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBS 5428T from M/s Lee Appraisal Services.
- b) Singapore Accident Statement of Vehicles FBS 5428T and SNB 1022D.
- c) Final Repair Bill of FBS 5428T from M/s Speedway Motor Pte Ltd.
- d) Colour damaged vehicle photographs of FBS 5428T.

Pre-Repair Inspection Date: 25/03/2022 at M/s Speedway Motor PL, 36 Toh Guan Road East #01-32 Enterprise Hub, Singapore 608580.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBS 5428T

Make & Model : Honda NSS300A

Year of Registration : 2021

Chassis Number : MLHNF0790J5000882

Engine Capacity : 279 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.