

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHB2451M/30/05/2022 14:21	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	fine *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	nei *22.00 FL
3	1		*REAR BUMPER MAT	0.00	0.00	mtk *50.00 F
4	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	cur *451.25 FL
5	1		*REAR BUMPER CENTRE LOWER MOULDING	20.00	0.00	mtk *155.00 FL
6	1		*REAR BUMPER TOW COVER	20.00	0.00	de *98.80 FL
7	1		*REAR NUMBER PLATE	0.00	0.00	Cur *50.00 F
8	1		*REAR BUMPER BEAM	20.00	0.00	X *394.80 FL
9	1		*REAR FOG LAMP	20.00	0.00	2 *201.50 FL
10	1		*ANTENNA ASSY - SMARTK	20.00	0.00	2 *40.50 FL
11	1		*ADVERTISEMENT LOGO - FENDER	0.00	0.00	nei *200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,123.25
- List Item Discount on L Items (S\$)	364.65
Total Parts (S\$)	1,758.60

ComfortDelGro Engineering Pte Ltd/SHB2451M/30/05/2022 14:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1031.45
20% 825.16
SN 250

2, 2:21 PM

Repairer Estimates

Estimates on Miscellaneous Items

o Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	400.00
2	SPRAYPAINT	New	250	300.00
3	CHECK WIRING	New	114	50.00
4	REMOVE/REFRIG REVERSE SENSOR	New	30	50.00

Gross Labour Cost (\$)

630

800.00

ComfortDelGro Engineering Pte Ltd/SHB2451M/30/05/2022 14:21. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97445749
 'up' 31/5/22 @ 4pm
 2 days
 c/s Rising after repair
 tanpin@lhand.com.

825.16
 250
 11
 630
 1716.16
 481350
 2 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: