



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: jeslyn@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Insurance Company:

Address:

Telephone:

Fax:

Make/ Model :

Hyundai

Chassis No :

KMHLN41ETMU066657

Date/Time of Accident :

21/05/2022 - 0625 HRS

Vehicle No:

SDS 5425 C

Acknowledged by Repairer

Signature:

Collision Type:

Head to Side

Date:

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	Outer Rear Quarter Panel, LH <i>bus</i>	1	\$ 1,892.00		\$ 1,892.00
2	Inner Rear Quarter Panel, LH	1			\$ -
3	Rear Door Shell, LH <i>bus</i>	1	\$ 2,147.90		\$ 2,147.90
4	Rear Door Trim Panel, LH <i>?</i>	1			\$ -
5	Belt Weather Strip, Window, Inner Rear Door, LH <i>X</i>	1			\$ -
6	Belt Molding, Window, Outer Rear Door, LH (Chrome) <i>?</i>	1	\$ 85.10		\$ 85.10
7	Trim, Quarter Panel, Outer, LH (Chrome)	1	\$ 45.00		\$ 45.00
8	Weather Strip, Rear Door Side, LH <i>?</i>	1	\$ 105.80		\$ 105.80
9	Weather Strip, Rear Body Side, LH <i>X</i>	1	\$ 95.80		\$ 95.80
10	Window Switch Assy, Rear Door, LH <i>X</i>	1	\$ 75.80		\$ 75.80
11	Water Deflector, Rear Door, LH <i>X</i>	1			\$ -
12	Hinge, Upper, Rear Door, LH <i>X</i>	1	\$ 45.90		\$ 45.90
13	Hinge, Lower, Rear Door, LH <i>X</i>	1	\$ 45.90		\$ 45.90
14	Striker, Rear Door, LH <i>X</i>	1	\$ 25.30		\$ 25.30
15	Checker Assy, Rear Door, LH <i>X</i>	1	\$ 47.30		\$ 47.30
16	Speaker, Rear Door, LH <i>X</i>	1			\$ -
17	Window Regulator Assy, Rear Door, LH <i>?</i>	1	\$ 223.40		\$ 223.40
18	Run Channel, Rear Door, LH <i>X</i>	1			\$ -
19	Guide Channel, Rear Door, LH <i>X</i>	1			\$ -
20	Outer Door Handle, Rear, LH <i>repair</i>	1	\$ 49.40		\$ 49.40
21	Inner Door Handle, Rear, LH <i>X</i>	1	\$ 48.20		\$ 48.20
22	Lock Assy, Rear, LH <i>?</i>	1	\$ 191.50		\$ 191.50
23	Rear Bumper <i>repair</i>	1	\$ 470.80		\$ 470.80
24	Rear Bumper Side Retainer, LH <i>X</i>	1	\$ 32.90		\$ 32.90
25	Fender Liner, Rear, LH <i>?</i>	1	\$ 75.00		\$ 75.00
TOTAL PARTS PRICE:				\$	5,703.00

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$	FINAL PRICE \$
1	Door Trim Panel Clips <i>?</i>	10	\$ 25.00	\$ 25.00
TOTAL SPECIAL NETT ITEM:				\$ 25.00

Labour Works / Panel Beating Related Works

Job Scope

TO REMOVE AND RENEW **LEFT REAR** DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS

Quotation

\$ 1,800.00 *800*

\$ 1,800.00

Spray Painting

Job Scope

TO RESPRAY AFFECTED AREAS

Quotation

\$ 1,000.00 *600*

\$ 1,000.00

Labour Works

Job Scope

TOWING

TO REMOVE/ REFIX WIRING CHECKS

TO TUFFCOAT AFFECTED AREA

TO REMOVE/ REFIX INTERIOR UPHOLSTERY

TO REMOVE/ REPLACE DOOR MECHANISM / PARTS

TO REPROGRAM ALL RELATED / NECESSARY SYSTEM

TO COMPUTERISED FOUR WHEEL ALIGNMENT

Quotation

\$ 20.00 *60*

\$ 40.00

\$ 60.00

\$ 80.00

\$ 100.00

\$ 120.00

OTHER LABOUR COST \$ 420.00 *60*

GRAND TOTAL

\$ 8,923.00

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua

Job Title: Motor Claim

Mobile: 65 9380 9969

Email: jeslyn@carzauto.com.sg

31/05/22 @ 1630

Resurvey after repair