



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: jeslyn@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company:	LKK Auto Consultants hence notify the Repairer of the following:		
Address:	- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed		
Telephone:	Fax:	Date:	31/5/22
Make/ Model:	Hyundai	Vehicle No:	SDS 5425 C
Chassis No:	KMHLN41ETMU066657	Acknowledged by Repairer	
Date/Time of Accident:	21/05/2022 - 0625 HRS	Signature:	Head to Side
Materials Cost/ Spare Parts Cost	Date:		

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	Outer Rear Quarter Panel, LH <i>buc /</i>	1	\$ 1,892.00		\$ 1,892.00
2	Inner Rear Quarter Panel, LH <i>X an</i>	1			\$ -
3	Rear Door Shell, LH <i>buc /</i>	1	\$ 2,147.90		\$ 1,923 2,147.90
4	Rear Door Trim Panel, LH <i>X an</i>	1			\$ -
5	Belt Weather Strip, Window, Inner Rear Door, LH <i>X an</i>	1			\$ -
6	Belt Molding, Window, Outer Rear Door, LH (Chrome) <i>m /</i>	1	\$ 85.10		\$ 85.10
7	Trim, Quarter Panel, Outer, LH (Chrome)	1	\$ 45.00		\$ 45.00
8	Weather Strip, Rear Door Side, LH <i>m /</i>	1	\$ 105.80	4525.60	\$ 105.80
9	Weather Strip, Rear Body Side, LH <i>X an</i>	1	\$ 95.80		\$ 95.80
10	Window Switch Assy, Rear Door, LH <i>X an</i>	1	\$ 75.80	20%	\$ 75.80
11	Water Deflector, Rear Door, LH <i>X an</i>	1			\$ -
12	Hinge, Upper, Rear Door, LH <i>X an</i>	1	\$ 45.90	3620.64	\$ 45.90
13	Hinge, Lower, Rear Door, LH <i>X an</i>	1	\$ 45.90		\$ 45.90
14	Striker, Rear Door, LH <i>X an</i>	1	\$ 25.30		\$ 25.30
15	Checker Assy, Rear Door, LH <i>X an</i>	1	\$ 47.30		\$ 47.30
16	Speaker, Rear Door, LH <i>X an</i>	1			\$ -
17	Window Regulator Assy, Rear Door, LH <i>? cra /</i>	1	\$ 223.40		\$ 223.40
18	Run Channel, Rear Door, LH <i>X an</i>	1			\$ -
19	Guide Channel, Rear Door, LH <i>X an</i>	1			\$ -
20	Outer Door Handle, Rear, LH <i>repar /</i>	1	\$ 49.40		\$ 49.40
21	Inner Door Handle, Rear, LH <i>X an</i>	1	\$ 48.20		\$ 48.20
22	Lock Assy, Rear, LH <i>? cra / m</i>	1	\$ 191.50		\$ 191.50
23	Rear Bumper <i>repar /</i>	1	\$ 470.80		\$ 470.80
24	Rear Bumper Side Retainer, LH <i>X an</i>	1	\$ 32.90		\$ 32.90
25	Fender Liner, Rear, LH <i>? X an</i>	1	\$ 75.00		\$ 75.00
TOTAL PARTS PRICE:					\$ 5,703.00

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$	FINAL PRICE \$
1	Door Trim Panel Clips <i>m /</i>	10	\$ 25.00	\$ 25.00
TOTAL SPECIAL NETT ITEM:				\$ 25.00

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW LEFT REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 1,892.00
	\$ 800.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,000.00
	\$ 600.00

Labour Works

Labour Works	Job Scope	Quotation
TOWING	PAID 320 118 9001068	\$ 20.00
TO REMOVE/ REFIX WIRING CHECKS		\$ 40.00
TO TUFFCOAT AFFECTED AREA		\$ 60.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY		\$ 80.00
TO REMOVE/REPLACE DOOR MECHANISM / PARTS		\$ 100.00
TO REPROGRAM ALL RELATED / NECESSARY SYSTEM		\$ 120.00
TO COMPUTERISED FOUR WHEEL ALIGNMENT		\$ 420.00
OTHER LABOUR COST		\$ 420.00

GRAND TOTAL \$ 8,923.00

CARZ AUTO SERVICES PTE LTD
 Person Incharge: Ms Jeslyn Chua
 Job Title: Motor Claim
 Mobile: 65 9380 9969
 Email: jeslyn@carzauto.com.sg