

AXA Insurance Pte Ltd

9 North Buona Vista Drive, #18-01/06

The Metropolis Tower 1

Singapore 138588

Tel: 1800-8804-888 Fax: 6880 4740 / 6880 5501

Attn : Motor Claim Department

VEHICLE NO : GBL 190 Y

MAKE / MODEL : TOYOTA HIACE DX 2.8 AUTO

CHASSIS NO : GDH2012016643

OWN INSURANCE : China Taiping Insurance (S) Pte. Ltd

POLICY NO : DMCVSNA00049482100

D.O.A : 04/01/2022 13:30

CLAIM DETAIL : LIST PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	RH SLIDE DOOR <i>X R</i>	1	\$ 2,299.32	\$ 2,299.32
2	RH SLIDE DOOR WEATHERSTRIP <i>X NN</i>	1	\$ 143.40	\$ 143.40
3	RH SLIDE DOOR GLASS MOULDING <i>X NN</i>	1	\$ 153.50	\$ 153.50
4	RH REAR QUARTER PANEL <i>/ M</i>	1	\$ 1,921.89	\$ 1,921.89
5	RH REAR QUARTER MUDFLAP <i>X NN</i>	1	\$ 209.44	\$ 209.44
6	RH REAR QUARTER AIR VENT <i>X NN</i>	1	\$ 112.35	\$ 112.35
7	RH TAILLAMP <i>X NN</i>	1	\$ 418.00	\$ 418.00
8	REAR BUMPER <i>/ M</i>	1	\$ 698.00	\$ 698.00
9	REAR BUMPER SIDE RETAINER RH <i>X NN</i>	1	\$ 55.00	\$ 55.00
10	REAR BUMPER UPPER COVER RH <i>X NN</i>	1	\$ 298.00	\$ 298.00
11	REAR BUMPER UPPER COVER RETAINER RH <i>X NN</i>	1	\$ 69.84	\$ 69.84

TOTAL PRICE : \$ 6,378.74

LIST LESS 25% : \$ 1,594.69

SUB TOTAL PRICE : \$ 4,784.06
CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/N PRICE
1	RH SLIDE DOOR GLASS SEALANT <i>X NN</i>	1	\$ 60.00	\$ 60.00
2	RH SLIDE DOOR INNER BOARD CLIP SET <i>X NN</i>	1	\$ 50.00	\$ 50.00
3	RH REAR QUARTER PANEL GLASS SEALANT <i>/ M</i>	1	\$ 60.00	\$ <i>40</i> 60.00
4	REAR BUMPER CLIPS SET <i>/ M</i>	1	\$ 50.00	\$ <i>30</i> 50.00
5	RH REAR TYRE <i>X NN</i>	1	\$ 250.00	\$ 250.00
6	TAILLAMP PROTECTOR SET <i>X NN</i>	1	\$ 180.00	\$ 180.00

S/NETT TOTAL PRICE \$ 650.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE
1	LABOUR CHARGE TO CHECK ELECTRICAL WIRING AND TEST REAR LIGHT FUNCTIONALITY	\$ 30 120.00
2	LABOUR CHARGE FOR PANEL BEATING, STRAIGHTENING, REMOVE-REFIT AND PARTS REPLACEMENT	\$ 800 1,200.00
3	TO SPRAY PAINT TO AFFECTED PANELS	\$ 400 1,000.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING TO CHECK THE CENTRAL LOCKING SYSTEM FOR PRPPER FUNCTION	\$ X 120.00
5	TO REMOVE AND REFIT RH SLIDING DOOR GLASS	\$ X 120.00
6	TO REMOVE AND REFIT REAR QUARTER PANEL GLASS	\$ 120.00
7	LABOUR CAHRGE TO CONDUCT WATER LEAKAGE TEST	\$ 30 80.00

LABOUR TOTAL PRICE: \$ 2,760.00

Steve (LKK)
31/5/22, 4.17p

W R
5 dgs
L/S
M M sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: