



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22005185/Tvy3m4

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 26/09/2022

ATTN: CHARLOTTE

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 9279Y	Veh. Inspected	SBS 8290C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1172492-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	31/05/2022

### 2. Vehicle Particulars & Condition

Make & Model	SCANIA KUB4X2	c.c	8867
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	YS2K4X20001861272	Colour	MULTI
Odometer	1127093 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	16/05/2022	Inspect Date / Time	31/05/2022 ( 02:33 PM )
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------