



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HL ASSURANCE PTE LTD 11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057			Ref: CS3/HLA22005188/Rqy3m4 Date: 11/08/2022 Code: HLA	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLL 330S	Veh. Inspected	SKJ 5745T	
Policy No.	MP312003	Coverage (\$)	0.00	
Claim No.	MPC03462/JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	31/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN PASSAT 1.4 TSI	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WVWZZZ3CZDP029577	Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/05/2022	Inspection Date	02/08/2022	
Survey held at	Blk 7 Sin Ming Industrial Estate Sector C #01-82			
Repairer	GUAN AUTO SERVICE			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				