

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 2022 22005039FR Date: 04<sup>th</sup> Oct 2022

Our Ref: CS6/AIS22005194/Vqy3m4

## M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

## DESKTOP SURVEY OF ACCIDENT VEHICLE SMQ 25K ACCIDENT ON 28/05/2022

We thank you for your instruction on 01/06/2022.

The following vehicle information was recorded:

Registration Number : SMQ 25K

Make & Model : B.M.W. 530E Iperformance Chassis Number : WBAJA92040CD03042

Year of Registration : 2020 Engine Capacity : 1998 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.