



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 31/05/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU10J028074		2ZR0B83934	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SMF4445M ACC DATE:29/05/22 TOW IN:29/05/22 @21:30 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				180.00	
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL FRT PORTION				1440.00	
4	B	BP-RES2 RESRPAY ACC AFF AREA FRT PORTION				1180.00	
5	L	BP-LPO SUPPLY REGN PLATE (PO#) FRT				80.00	
6	B	BP-LAB2 CONDUCT LEAK TEST REAR PORTION				180.00	
7	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR				180.00	
8	B	BP-LAB2 TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA				540.00	
9	B	BP-LAB2 REPL REAR WINDSCREEN				466.20	
10	Z	BP-BKT SUPPLY PHV STICKER				20.00	
11	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR				180.00	
12	B	BP-LAB2 R/I INTERIOR UPHOLSTERY TO FAC REPAIR				616.00	
13	Z	BP-SLANT SUPPLY SEALANT (NETT)3 PANEL				240.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		Amount Due
					Others		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			31/05/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J028074	2ZR0B83934	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	B	BP-LAB2 RESRPAY ACC AFF PARTS AND PANEL REAR POR TION				5760.00
15	B	BP-RES2 RESRPAY ACC AFF AREA REAR PORTION				3540.00
16	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				180.00
17	S	BP-SUBLET REPLACE REAR EXHAUST ASSY				360.00
18	1	U53102-47180 GRILLE SUB-ASSY,	1.00	597.00		597.00
19	2	U52128-47040 COVER, FR BUMPER	1.00	25.80		25.80
20	3	U52543-47030 SEAL, FR BUMPER	1.00	28.60		28.60
21	4	U52611-47100 ABSORBER, FR BUMPER	1.00	84.20		84.20
22	5	U53395-47030 SEAL, HOOD TO FR END	1.00	108.50		108.50
23	6	U52119-47969 COVER, FR BUMPER	1.00	589.50		589.50
24	7	U53111-47110 GRILLE, RADIATOR	1.00	510.10		510.10
25	8	U81070-47660 UNIT ASSY, HEADLAMP,	1.00	2678.10		2678.10
26	9	U81140-47660 UNIT ASSY, HEADLAMP,	1.00	2678.10		2678.10
27	0	U75310-33050 EMBLEM ASSY,	1.00	112.30		112.30
28	1	U75441-47130 PLATE, LUGGAGE COMPT	1.00	58.00		58.00
29	2	U75442-47080 PLATE, BACK DOOR	1.00	67.20		67.20
30	3	U52016-47060 ARM SUB-ASSY, RR	1.00	186.30		186.30
31	4	U52015-47080 ARM SUB-ASSY, RR	1.00	186.30		186.30
32	5	U52023-12240 REINFORCEMENT	1.00	230.20		230.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			31/05/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J028074	2ZR0B83934	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
33	6	U52159-47912 COVER, RR BUMPER	1.00	589.50		589.50
34	7	U52156-47010 SUPPORT, RR BUMPER	1.00	151.20		151.20
35	8	U52155-47010 SUPPORT, RR BUMPER	1.00	151.20		151.20
36	9	U52576-47030 RETAINER, RR BUMPER	1.00	62.70		62.70
37	0	U52575-47030 RETAINER, RR BUMPER	1.00	62.70		62.70
38	1	S52161-0K040 PIECE, RR BUMPER	1.00	4.30		4.30
39	2	U76891-47040 SPOILER, RR NO.1	1.00	899.70		899.70
40	3	U58307-47080 PANEL SUB-ASSY, BODY	1.00	738.00		738.00
41	4	U58311-47091 PAN, RR FLOOR	1.00	739.90		739.90
42	5	U67935-47010 C0 PLATE, BACK DOOR	1.00	192.50		192.50
43	6	U58410-47011 C0 BOARD ASSY, DECK	1.00	575.40		575.40
44	7	U68105-47190 GLASS SUB-ASSY, BACK	1.00	1093.60		1093.60
45	8	U56117-50140 DAM, WINDOW GLASS	1.00	30.60		30.60
46	9	U67881-47040 WEATHERSTRIP, BACK	1.00	355.10		355.10
47	0	U67005-47460 PANEL SUB-ASSY, BACK	1.00	1177.30		1177.30
48	1	U67750-47050 C0 BOARD ASSY, BACK	1.00	348.70		348.70
49	2	U69350-28151 LOCK ASSY, BACK DOOR	1.00	437.70		437.70
50	3	U81551-47262 LENS & BODY, RR	1.00	730.90		730.90
51	4	U81561-47252 LENS & BODY, RR	1.00	706.10		706.10
52	5	U17430-37480 PIPE ASSY, EXHAUST	1.00	798.70		798.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			31/05/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J028074	2ZR0B83934	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
53	6	U17565-22040 SUPPORT, EXHAUST	2.00	52.20		104.40
54	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
55	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
56	9	TREVSE-47006 221 BACK SENSOR BLACK AGEHA	1.00	101.05		101.05

For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd						33,849.65	
		Please acknowledge receipt of vehicle		Parts		GST 7.00%	
				Labour		2,369.48	
				Sublet		Less	
				Lubrication/Fluid		0.00	
				Others		Amount Due	
						36,219.13	

Customer Copy