

SIN U LIAN MOTOR REPAIR AND TRANSPORT

61 WOODLANDS INDUSTRIAL PARK E9 S757047 #07-K1

EMAIL: SULREPAIR@GMAIL.COM

UEN: 21825000B

HP: 9689 3555

Date of Estimate: 1 June 2022
Vehicle Number: PC 5196 E
Name of Registered Owner: SIN U LIAN TRAVEL & COACH PTE LTD
Date of Accident: 22 Apr 20222
Manufacturer: YUTONG
Model: ZK6107HE
Chassis Number: LZYTBD65G1038579

ESTIMATION FOR ACCIDENT VEHICLE NOS PC 5196 E

PARTS

	ITEM	QUANTITY	COST (SGD \$)	
			PER UNIT	TOTAL
1	WINDSCREEN	1	\$ 1,950.00	\$ 1,950.00
2	SIDE MIRROR	1	\$ 494.00	\$ 494.00
3	HEAD LAMP LH	1	\$ 390.00	\$ 390.00
4	WIPER LINK	1	\$ 130.00	\$ 130.00
5	WIPER BLADE	1	\$ 39.00	\$ 39.00
6	WIPER ARM	1	\$ 58.00	\$ 58.00
7	DOOR SCREEN	1	\$ 364.00	\$ 364.00
8	FRONT PANEL	1	\$ 416.00	\$ 416.00
9	WIPER MOTOR	1	\$ 299.00	\$ 299.00
		SUB TOTAL		<u>\$ 4,140.00</u>

LABOUR

	ITEM	TOTAL (SGD\$)
1	BODY REPAIR	\$ 3,500.00
2	SPRAY PAINTING ON AFFECTED AREA	\$ 2,500.00
3	WINDSCREEN REPAIR	\$ 1,200.00
4	DOOR SCREEN REPAIR	\$ 300.00
5	WIRING	\$ 100.00
		SUB-TOTAL
		<u>\$ 7,600.00</u>

LOSS ON USE

25 DAYS X \$650

SUB-TOTAL \$ 16,250.00

ESTIMATED GRAND TOTAL **\$27,990.00**

PLEASE NOTE THE ABOVE IS ONLY AN ESTIMATE.