



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22005213/Evy3m4 Date: 02/09/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1003E	Veh. Inspected	SMR 20T	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/22/2059	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	01/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW X4	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBAXW120000R68581	Colour	WHITE	
Odometer	70609 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	CINTURATO	4 mm	
L/H Front Tyre	245/50 R18	CINTURATO	4 mm	
R/H Rear Tyre	245/50 R18	CINTURATO	4 mm	
L/H Rear Tyre	245/50 R18	CINTURATO	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/05/2022	Inspection Date	21/06/2022	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	