

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0413/2022/JT

30-Jun-22

CHANG

1 of 1

SLG 8865 P


AUDI A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REPAIR RHS TAILLAMP PANEL.	\$ 700.00	250
2	TO RESPRAY RHS TAILLAMP PANEL.	\$ 1,050.00	550
GRAND TOTAL		\$ 1,750.00	

Repair days: 4+1

= 5

For Premium Automobiles Pte Ltd


Authorised Signature