

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| UNITED OVERSEAS INSURANCE LTD Ref: CS/UC 146 ROBINSON ROAD Date: 29/07/ #02-01 UOI BUILDINGSINGAPORE 068909 Code: UOI2 1. Policy Particulars :- THIRD PARTY CLAIM | OI22005241/Uvy3m4 | |
|--|--|--|
| #02-01 UOI BUILDINGSINGAPORE 068909 Code: UOI2 | / | |
| | /2022 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | |
| | 1. Policy Particulars :- THIRD PARTY CLAIM | |
| Insured Veh. GBG 998K Veh. Inspected SMQ 9 | 500E | |
| Policy No. Coverage (\$) 0.00 | | |
| Claim No. M11D15412206 Excess (\$) 0.00 | | |
| Assign From JOSEPHINE WONG Assign Date 02/06/ | /2022 | |
| 2. Vehicle Particulars & Condition | | |
| Make & Model MERCEDES BENZ S500 AMG LINE M-HYBRID (A) c.c 2999 | | |
| Engine No. HIDDEN Year of Reg. 2020 | | |
| Chassis No. WDD2221602A514073 Colour BEIGE | E | |
| Odometer 36894 KM Steering IN OF | RDER | |
| Brakes IN ORDER Modification SPOR | RTS RIM | |
| General GOOD | | |
| 3. Conditions of Tyres | | |
| Size Make Balar | nce | |
| R/H Front Tyre 245/40 R20 CONTINENTAL 6 mm | | |
| L/H Front Tyre 245/40 R20 CONTINENTAL 6 mm | | |
| R/H Rear Tyre 275/35 R20 CONTINENTAL 6 mm | | |
| L/H Rear Tyre 275/35 R20 CONTINENTAL 6 mm | | |
| 4. Description of Damages | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | |
| DAMAGES SEE DETAILS. | | |
| 5. General Information | | |
| Accident Date 20/05/2022 Inspection Date 02/06/ | /2022 | |
| Survey held at SPECIALISTS MOTOR PTE LTD | | |
| BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711 | | |
| 5a. Remarks | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | |
| 5b. Estimate Days of Repair | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | |