

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD6751K
MAKE 08.04.2016
MODEL MERC E6

DATE 31.05.2022
CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY <i>de</i>			\$1,510.00
1	REAR BUMPER REINFORCEMENT <i>?</i>			\$1,150.00
1	REAR BUMPER LOWER COVER <i>X</i>			\$325.00
1	REAR BUMPER BRACKET LH/RH <i>X</i>		\$135.00	\$270.00
1	REAR PANEL END <i>X</i>			\$1,380.00
1	REARBUMPER TOW COVER <i>X</i>			\$175.00
	SUB TOTAL			\$4,810.00
	LESS 20%			\$962.00
				\$3,848.00
1	REVERSE SENSOR <i>X</i> NN			\$388.00
				\$349.20
	Labour Charge			
	Panel Beating			\$750.00 <i>400</i>
	Spray Painting Charge			\$400.00 <i>250</i>
	Tuff kote			\$80.00 <i>X</i>
	Check Wiring			\$60.00 <i>X</i>
	Remove/refix reverse sensor			\$60.00 <i>40</i>
	TOTAL LABOUR			\$1,350.00
	ESTIMATE TOTAL			\$5,547.20
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2 Days.
L/S
After repair photos.
Gino Riap
01/6/22
4pm.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to negotiation
- Third party survey on "no win no fee" basis
- No illegal modification
- Supplemental charges are subject to approval and is subject to final approval by insurance company

Acknowledged by Repairer

Signature:

Date: