

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd DATE: 23/08/2022

Survey details

| Date of loss | 1/6/2022 |
|---------------------|-----------------|
| Date of appointment | 3/6/2022 |
| Date of survey | 6/6/2022 |
| Location of survey | SUN FATT MOTORS |

Vehicle Details:

| Claim Type: | THIRD PARTY |
|----------------------|----------------------------------|
| Vehicle number | SLX 6283S |
| Make and Model | TOYOTA CAMRY 2.0 AUTO ABS AIRBAG |
| Date of registration | 25/9/2008 |
| Excess | |
| Market Value | \$61,000.00 |
| Parf Rebate | \$20,369.00 |
| Nett Loss | \$40,631.00 |

Repair details

| Initial Estimate | \$8,607.98 |
|------------------|------------|
|------------------|------------|

Proposed/Revised repair cost:

| Parts | \$4,611.08 |
|--------------------------|---------------|
| "Check items (Estimated) | |
| Labour | \$950.00 |
| Total | \$5,561.08 |
| Lump Sum (Estimated) | \$4,450.00 |
| | |
| Number of days of repair | 05 Days (Est) |

| _ | | | | | _ | |
|---|-----------------------|---|-----|---|-----|-----|
| R | | | _ | 1 | ı., | ~ - |
| к | $\boldsymbol{\omega}$ | m | • • | r | Z. | |
| | | | | | | |

The vehicle sustained damages at the N/S body.

We have Not Authorize repair.