

Ref to Adrian on

20/6/22

TP Chin
Veron.

1932
1545.60

1130.

total: 2875.60

4/5 : 2150

3 Days.

2150

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
Estimate of Cost of Repairs				
		Date	19-Jun-2022	
		Vehicle No.	SMS4191B	
		Model	Hyundai Avante	
		CHASSIS/ENG#	KMHD841CMLUO29854	
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	RH Front Door <i>dented</i>	1	\$1,904.70	\$1,904.70 <i>1775</i>
2	RH Door Sticker <i>MC</i>	1	\$22.00	\$22.00 ✓
3	RH Outer Handle <i>at</i>	1	\$135.00	\$135.00 ✓
4	RH Rear Door <i>Phys</i>	1	\$2,147.90	\$2,147.90 X
5	RH Rear Door Sticker <i>new</i>	1	\$22.00	\$22.00 X
Sub-total 1				\$4,231.60
Sub-total 2				\$-00
LABOUR				
1	Spray paint RH front & rear door, locker panel		\$800.00	<i>600</i>
2	Transfer door component		\$100.00	<i>80</i>
3	Knock & change parts		\$600.00	<i>400</i>
4	Tuff kote		\$80.00	<i>50</i>
Labour Total				\$1,580.00
Parts & Labour Total				\$5,811.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: