

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1744 (4 lines) FAX: 6483 0170 Email: ahlimnc@singnet.com.sg
 GST M9-0009639-E RCB NO-06470300B

SURVEYOR COPY

M/S : NG WAI MUN
 14 DEDAP PLACE
 SINGAPORE 809513

Estimate No: MC1902730
 Date: 03 Jun 2022
 Policy No: MT/00574157/03
 Veh Reg No: SLR2068E
 Make/Model: SUZUKI SWIFT 1.6 MT

ATTN:
 Your Ref No: SLR2068E
 Claim Type: Third Party → *CFIUA*
 Accident Date: 01/06/2022
 TP Veh Reg No: SLU6466Y

LKC
130
Not Ashamed
61 Day @ 2600\$
Perman After Paint
JSAEFC31S00202177

Estimate Repair Cost to Vehicle No :SLR2068E

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BUMPER <i>71811-37K01-799</i>	1 PC	<i>nu</i> 769.50	<i>✓</i>
2 REAR BUMPER LOWER GRILLE <i>71841-37K00-2K2</i>	1 PC	<i>CM</i> 1,621.40	<i>✓</i>
3 REAR BUMPER LOWER GRILLE CTR COVER	1 PC	<i>nu</i> 35.70	<i>✓</i>
4 REAR BUMPER REINFORCEMENT BKT	2 PC	<i>R</i> 56.10	<i>X</i>
5 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>SK</i> 50.00	<i>X</i>
6 REAR BUMPER CLIPS	4 PC	<i>nu</i> 20.00	<i>✓</i>
7 REAR BUMPER NO PLATE LAMP LH & RH	1 2PC	<i>CM</i> 53.60	<i>2X</i>
8 REAR FENDER COWLING CLIPS	8 PC	<i>nu</i> 40.00	<i>X</i>
		2,646.30	
	Less 15%	396.95	2,249.36
Special Nett			
9 REAR VIEW CAMERA - CHECK PRICE <i>Zila</i>	1 PC	<i>Short</i> 200	<i>✓</i>
10 NUMBER PLATE	1 PC	<i>CM</i> 35.00	<i>✓</i>
11 REVERSE SENSOR	1 SET	<i>Short</i> 200.00	<i>✓</i>
		235.00	235.00
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>100</i>
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>50</i>
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>nu</i> 60.00	<i>X</i>
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>300</i>
16 TO SPRAY REAR BUMPER,REAR END PANEL	1 PC	500.00	<i>300</i>
		1,160.00	1,160.00

3844.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: