

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : NG WAI MUN
 14 DEDAP PLACE
 SINGAPORE 809513

Estimate No: MC1902730
 Date: 03 Jun 2022
 Policy No: MT/00574157/03
 Veh Reg No: SLR2068E
 Make/Model: SUZUKI SWIFT 1.6 MT

ATTN:
 Your Ref No: SLR2068E
 Claim Type: Third Party → (FINA)
 Accident Date: 01/06/2022
 TP Veh Reg No: SLU6466Y

LKE
 130

Not Ashailed
11 Day &
Resurvey After Paint
2-3 days

Estimate Repair Cost to Vehicle No :SLR2068E

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	<i>an</i> 769.50	✓
2 REAR BUMPER LOWER GRILLE	1 PC	<i>cm</i> 1,621.40	✓
3 REAR BUMPER LOWER GRILLE CTR COVER	1 PC	<i>nt</i> 35.70	✓
4 REAR BUMPER REINFORCEMENT BKT	2 PC	56.10	?
5 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>sn</i> 50.00	X
6 REAR BUMPER CLIPS	4 PC	<i>an</i> 20.00	✓
7 REAR BUMPER NO PLATE LAMP LH & RH	2 PC	53.60	?
8 REAR FENDER COWLING CLIPS	8 PC	<i>an</i> 40.00	X
		2,646.30	
	Less 15%	396.95	2,249.36
Special Nett			
9 REAR VIEW CAMERA - CHECK PRICE	1 PC	<i>short</i> 0.00	✓
10 NUMBER PLATE	1 PC	<i>cm</i> 35.00	✓
11 REVERSE SENSOR	1 SET	200.00	?
		235.00	235.00
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>10d</i>
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>5d</i>
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>an</i> 60.00	X
15 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>200d</i>
16 TO SPRAY REAR BUMPER, REAR END PANEL.	1 PC	500.00	<i>200d</i>
		1,160.00	1,160.00

Zila
 Ah Lim Motor Company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/06/2022 17:55 (SGT)
Date of Accident	01/06/2022 22:10 (SGT)
Exact Location of Accident	Ang Mo Kio Ave 5, Singapore
Additional Location Information	AMK AVE 5 TO CTE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR2068E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	NG WAI MUN
NRIC No	SXXXX401J
Email Address	XINYITEO30@GMAIL.COM
Mobile Phone No	(Phone) +65-98383082
Alternative Phone No	+65-84823570

VEHICLE PARTICULARS

Manufacturer	Suzuki
Model	Swift
Variant	SWIFT 1.6 MT
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Manual
CC	1586

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	MT/00574157/03
Cover Note Number	07/01/2022 - 06/01/2023

DRIVER

Name of Driver	TEO XIN YI
NRIC No	SXXXX958G

