

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Authorized
run
6/6/22
L/s \$18,500/
12 days.

VEHICLE No: GBD 1347Z

NETT ITEM

1PC	DROPSIDE GATE O/S	2201	DR	\$2,250.00	✓
1PC	DROPSIDE GATE LOWER MEMBER O/S		R	\$878.00	X
1PC	REAR MUDGUARD REAR O/S		DR	\$233.00	✓
1PC	REAR MUDGUARD FRONT O/S		DR	\$233.00	✓
1PC	REAR TAILGATE LOWER 'L' PANEL O/S	105.50	Surf	\$151.00	✓
1PC	REAR TAILGATE LOWER 'L' PANEL STOPPER O/S		Wrm	\$60.00	✓
1PC	FRONT WINDSCREEN	1095.30	Cne	\$1,488.20	✓
1PC	FRONT WINDSCREEN MOULDING		ner	\$128.20	✓
1PC	FRONT WIPER PANEL GARNISH		R	\$445.20	X
1PC	FRONT PANEL	1412.70	DR	\$1,915.20	✓
1PC	FRONT PANEL 'CABSTAR' EMBLEM		11	\$45.80	X
1PC	FRONT GRILLE	690	Cne	\$578.60	✓
1PC	FRONT GRILLE LOGO		ner	\$68.00	✓
2PCS	HEADLAMPS @\$ 600.00	518.50 x 2 = 1037	Cne	\$1,200.00	✓
2PCS	HEADLAMP TOP GARNISHS @\$350.00	215.20 x 2 = 430.40	Cne	\$700.00	✓
2PCS	HEADLAMP LOWER GARNISHS @\$60.00	45 x 2 = 90	Surf	\$120.00	✓
1PC	FRONT BUMPER	954	DR	\$945.00	✓
1PC	FRONT BUMPER BEAM	435.10	Surf	\$605.00	✓
2PCS	FRONT CORNER PANELS @\$389.90		DR	\$779.80	✓
1PC	AIR CON BLOWER		Surf	\$1,665.00	X
1PC	HEATER UNIT	1645.20	Cne	\$2,820.00	✓
1PC	FRONT MIRROR BRACKET ASSY N/S	281.50	Surf	\$688.50	✓
1PC	FRONT MIRROR ROUND N/S	85.00	Surf	\$145.00	✓
1PC	FRONT MIRROR RECTANGLE N/S	140.80	BRD	\$245.00	✓
1PC	FRONT MIRROR O/S	144.30	Cut	\$245.00	✓
1PC	FRONT MIRROR BRACKET O/S	265.50	Cne	\$350.00	✓
1PC	FRONT DOOR OUTER PILLAR N/S		DR	\$899.10	✓
2PCS	FRONT DOORS @\$1900.00	1474.10 x 2 = 2948.20	DR	\$3,800.00	✓
2PCS	FRONT DOOR OUTER SIGNAL LAMPS @\$160.00	54.60 x 2 = 109.20	Surf	\$320.00	✓
2PCS	FRONT DOOR INNER LOCKS @\$350.00	172.30 x 2 = 344.60	m/jm	\$700.00	✓
2PCS	FRONT DOOR OUTER GLASS MOULDINGS @\$150.00		11	\$300.00	X
2PCS	FRONT DOOR HINGES @\$100.00		Surf/ner	\$200.00	✓
2PCS	FRONT DOOR CHECKERS @\$90.00		Wrm	\$180.00	✓
2PCS	FRONT DOOR GLASS REGULATORS @\$450.00	x 2 = 235.20	jm	\$900.00	✓
2PCS	FRONT DOOR INNER TRIM BOARDS @\$850.00	1513.80	ner/Cne	\$1,700.00	✓
2PCS	FRONT DOOR INNER RUBBERS @\$145.00	144.60 x 2 = 289.20	Wrm	\$290.00	✓
2PCS	FRONT DOOR INNER AIR VENTS @\$80.00	65 x 2 = 130	Wrm	\$160.00	✓
2PCS	FRONT STEP GARNISHS @\$320.00	181.10 x 2 = 362.20	Surf	\$640.00	✓
1PC	AIR CON CONDENSER	988.20	DR	\$1,050.00	✓
1PC	AIR CON FAN ASSY	480	Surf	\$980.00	✓

(102)

2PCS	FRONT SHOCK ABSORBERS @\$250.00	su	\$500.00	X
2PCS	FRONT LOWER ARMS @\$900.00	wopul 580.50 x 2 = 1161.00	\$1,800.00	/
2PCS	FRONT KNUCKLE ARMS @\$1150.00	berf 980.30 x 2 = 1960.60	\$2,300.00	/
2PCS	FRONT WHHEL HUB BEARINGS @\$600.00	R dyed 455 x 2 = 910	\$1,200.00	/
1PC	FRONT ENGINE CROSS MEMBER		\$820.00	X
			<u>110%</u>	
			\$37,721.60	

S.NETT

1SET	DROPSIDE GATE CORPORATE STICKER O/S	neu	\$500.00	300
1SET	REAR CANOPY ASSY	R	\$1,000.00	X
1PC	REAR STEEL RIM O/S	R	\$80.00	X
2SET	FRONT DOOR CORPORATE STICKERS @\$450.00	neu	\$900.00	500
1SET	FRONT DOOR 'ROC' STICKERS @\$50.00	neu	\$100.00	60
2PC	FRONT STEEL RIMS @\$80.00	berf	\$160.00	100
2PC	FRONT TYRES @\$200.00	pur	\$400.00	180 200
1PC	FRONT WINDSCREEN SEALANT	neu	\$50.00	40
1PC	FRONT WINDSCREEN INNER SEAL	neu	\$50.00	40
1PC	FRONT LICENCE PLATE	suc	\$50.00	X
1PC	REAR RAILING TOP O/S	su	\$500.00	X
			\$50.00	30
TO CHECK WIRING			\$160.00	120
TO SPRAY RUST PROOFING			\$150.00	100
TO DISMANTLE & REFIX FRONT WINDSCREEN			\$380.00	200
TO DISMANTLE & REFIX FRONT DASHBOARD			\$180.00	120
TO DISMANTLE & REPLACED AIR CON BLOWER			\$150.00	120
TO REFIX AIR CON GAS			\$500.00	300
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE			\$100.00	60
TO CONDUCT WHEEL ALIGNMENT			\$180.00	100
TO TRANSFER FRONT DOOR MECHANISM			\$2,280.00	1600
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$2,200.00	1500
TO PUTTY & SPRAY PAINTING				
TOTAL			\$47,841.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S.N-1240
L-4130