

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3068/06/22

Your Ref:

Date: 7th JUNE 2022

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Name Of Insured : Mr Low Boon Keng
Date Of Accident : 05/06/22 (23:45hrs)
Policy Number : D22MPC00Q2769

Estimate cost of repair to HYUNDAI ELANTRA 1.6 (A) Saloon - SLS 2960 Z

1 pc front n/s side mirror	cur/Dave	\$ 638.00	✓
1 pc front n/s door	surf	1,904.00	✓
1 set front n/s door fram sticker	ner	56.00	✓
15 pcs front n/s door inner trim board clips	@ \$ 6.00	90.00	X
1 pc rear n/s door	DD/surf	1,878.00	✓
1 set rear n/s door frame sticker	ner	46.00	✓
16 pcs rear n/s door inner trim board clips	@ \$ 6.00	96.00	X
8 pcs rear n/s fender inner shield clips	@ \$ 3.50	28.00	X
10 pcs rear bumper clips	@ \$ 3.50	35.00	✓
1 pc rear bumper n/s side retainer	ner	45.00	X
1 pc rear n/s sport rim	cur	671.00	✓
		\$ 5,487.00	
	Less 20%	\$ 1,097.40	
		\$ 4,389.60	

To wiring check up for affected wiring system.	45.00	20
--	-------	----

To remove & refix front & rear n/s door inner trim board cover, glass, moulding, weatherstrip, handle, garnish & necessary parts, to enable repair necessary parts. 240.00 100

To remove & refix oushion seat, rear n/s fender inner shield, carpet, floor mat, garnish & necessary parts, to enable repair rear n/s fender & necessary parts. 120.00

To check & adjust wheel alignment & balancing.	120.00	6.0
--	--------	-----

To respray painting on all affected accident parts.	1,500.00	1102
---	----------	------

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. 1,300.00 \$10

\$ 7,714.60

Dollars : Seven Thousand Seven Hundred Forteen And Cents Sixty Only.

HUP MOTOR TRADING & SERVICE

[illegible]
$$\begin{array}{r} 5328 \\ 202 \\ \hline 4182 \\ 1910 \end{array}$$

(08/11/13) Wei

ASS. REC. BY: Marcus

REF:

CS/11122005-392/4ry3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

SL52960X
Imp motor

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

856k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

L7492800

Veh No:

SL5 29602

Yr Regn:

19/09/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra GLS c.c 1591

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

110150

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH D841CMJUCU2010

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil S/Rim / STD A/Rim or

Tyre Size:

F: 215/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

05/06/22

D.O.I.

09/06/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chasals frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 900

4/5 to 4800 informed Rand.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) \$ + RS. \$



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

686F

Vehicle Details

Vehicle No.:

SLS2960Z

Vehicle to be Exported:

No

Intended Deregistration Date:

08 Jun 2022

Vehicle Make:

HYUNDAI

Vehicle Model:

ELANTRA AD 1.6 GLS AT

Primary Colour:

Red

Manufacturing Year:

2017

Engine No.:

G4FGHU620782

Chassis No.:

KMHD841CMJU542010

Maximum Power Output:

93.8 kW (125 bhp)

Open Market Value:

\$12,674.00

Original Registration Date:

19 Sep 2017

First Registration Date:

19 Sep 2017

Transfer Count:

1

Actual ARF Paid:

\$12,674.00 6337

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

18 Sep 2027

PARF Rebate Amount:

\$9,505.00

Intended COE Rebate Details

COE Expiry Date:

18 Sep 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$36,001.00

COE Rebate Amount:

\$19,000.00

Total Rebate Amount:

\$28,505.00

The Information contained herein is correct as at 08 Jun 2022

OK