

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3068/06/22

Your Ref: _____

Date: 7th JUNE 2022

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Name Of Insured : Mr Low Boon Keng
Date Of Accident : 05/06/22 (23:45hrs)
Policy Number : D22MPC0002769

Estimate cost of repair to HYUNDAI ELANTRA 1.6 (A) Saloon - SLS 296Q Z

1 pc front n/s side mirror	cur/Dave	\$ 638.00	✓
1 pc front n/s door	Surf	1,904.00	✓
1 set front n/s door fram sticker	ner	56.00	✓
15 pcs front n/s door inner trim board clips	ner	90.00	X
1 pc rear n/s door	DD/Surf	1,878.00	✓
1 set rear n/s door frame sticker	ner	46.00	✓
16 pcs rear n/s door inner trim board clips	ner	96.00	X
8 pcs rear n/s fender inner shield clips	ner	28.00	X
10 pcs rear bumper clips	ner	35.00	✓
1 pc rear bumper n/s side retainer	ner	45.00	X
1 pc rear n/s sport rim	cur	671.00	✓
		\$ 5,487.00	
	Less 20%	\$ 1,097.40	
		\$ 4,389.60	

To wiring check up for affected wiring system. 45.00 20

To remove & refix front & rear n/s door inner trim board cover, glass, moulding, weatherstrip, handle, garnish & necessary parts, to enable repair necessary parts. 240.00 100

To remove & refix cushion seat, rear n/s fender inner shield, carpet, floor mat, garnish & necessary parts, to enable repair rear n/s fender & necessary parts. 120.00 80

To check & adjust wheel alignment & balancing. 120.00 60

To respray painting on all affected accident parts. 1,500.00 1100

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. 1,300.00 550

\$ 7,714.60

Dollars : Seven Thousand Seven Hundred Forteen And Cents Sixty Only.

HUP MOTOR TRADING & SERVICE

Signature: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5228
202
4182
1910