

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Cecilia

not Adhant
ner
6/6/22
1/5 7800/
6 days.

VEHICLE No: SJM 6088X

1PC	FRONT BUMPER	re/turn	1615.00	\$2,205.00	/
1PC	FRONT BUMPER SIDE RETAINER O/S	one	110.00	\$145.00	/
1PC	FRONT BUMPER BEAM	surf	790.00	\$1,015.00	/
1SET	FRONT BUMPER CLIPS	ner		\$60.00	/
1PC	FRONT BUMPER UNDER COVER	sur		\$355.00	x
1PC	HEADLAMP O/S	one	1661.00	\$2,820.00	/
1PC	FRONT FENDER O/S	3 sides	850.00	\$1,165.00	/
1PC	FRONT FENDER INNER SHIELD O/S	both	181.00	\$295.00	/
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	ner		\$50.00	/
1PC	FRONT DOOR O/S	1		\$1,865.00	x
1PC	FRONT SPORT RIM O/S	cur/surf	980.00	\$1,100.00	/
1PC	FRONT SHOCK ABSORBER O/S	sur		\$485.00	x
1PC	FRONT KNUCKLE ARM O/S	surf		\$799.00	/
1PC	FRONT KNUCKLE ARM BEARING O/S	2ye	450.00	\$520.00	/
1PC	FRONT LOWER ARM O/S	surf	699.00	\$810.00	/
1PC	FRONT SUPPORT PANEL	one	102	\$955.00	/
				\$14,644.00	

TO CHECK WIRING	\$80.00	20
TO SPRAY RUST PROOFING	\$80.00	30
TO REFILL AIR CON GAS	\$120.00	100
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$180.00	60
TO CONDUCT WHEEL ALIGNMENT	\$120.00	100
TO DISMANTLE & REPLACED PARTS	\$1,200.00	600
TO PUTTY & SPRAY PAINTING	\$1,200.00	600
TOTAL	\$17,624.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2. 9200
102
8280
1510
9790
202
7832