



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM22005428/Apa3q2 Date: 06/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3844X	Veh. Inspected	SJZ 4272A
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M043C5	Excess (\$)	0.00
Assign From		Assign Date	07/06/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA AIRWAVE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GJ11208774	Colour	WHITE
Odometer	176934 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/06/2022	Inspection Date	13/06/2022
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	