

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Faiz Rosli

Date: 09 Jun 2022

Preliminary Advice

Vehicle No	: SLX1001Y	Accident Date	: 06/06/2022
Make	: HYUNDAI ACCENT	Policy No.	: SP2000790763
Assignment Date	: 08/06/2022	Excess	: S\$600.00
Date of Inspection	: 8/6/2022	Est. Duration of Repair	: 4
Inspection At	: VIN'S MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,088.00
Revised Amount	:S\$	2,398.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,398.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	26,727.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,273.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair as there is no second hand parts or recon parts.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .