

# Vin's

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd  
79 Robinson Road  
#09-01  
Singapore 068897

### Claim Details

Case Ref. No. : OD/062022/5465  
Date : 07-06-2022  
Accident Date : 06-06-2022

### Vehicle Details

Make & Model : Hyundai ACCENT (RB) 1.4 CVT  
Chassis No : KMHCU41BTJU414787  
Registration No : SLX1001Y

| S/N | Description                                         | Qty   | Amount (\$) |
|-----|-----------------------------------------------------|-------|-------------|
| 1   | RH HEADLAMP <i>broken</i>                           | 1.00  | \$400.00    |
| 2   | RH HEADLAMP LOWER BRACKET <i>broken</i>             | 1.00  | \$20.00     |
| 3   | FRONT BUMPER <i>crack</i>                           | 1.00  | \$280.00    |
| 4   | FRONT BUMPER RH FOG LAMP <i>crack</i>               | 1.00  | \$150.00    |
| 5   | FRONT BUMPER RH SIDE RETAINER <i>broken</i>         | 1.00  | \$20.00     |
| 6   | FRONT BUMPER SPONGE <i>new</i>                      | 1.00  | \$60.00     |
| 7   | FRONT BUMPER REINFORCEMENT <i>new</i>               | 1.00  | \$160.00    |
| 8   | FRONT BUMPER CLIPS @ \$2 <i>new</i>                 | 10.00 | \$20.00     |
| 9   | WIPER TANK <i>defunct</i>                           | 1.00  | \$50.00     |
| 10  | FRONT RH FENDER <i>dent</i>                         | 1.00  | \$240.00    |
| 11  | FRONT RH FENDER INNER SHIELD <i>new</i>             | 1.00  | \$40.00     |
| 12  | FRONT RH FENDER INNER SHIELD CLIPS @ \$2 <i>new</i> | 10.00 | \$20.00     |
| 13  | FRONT RH FENDER TRIANGLE PLATE (BLACK) <i>new</i>   | 1.00  | \$20.00     |

\$1,480.00

Margin: 10%

\$148.00

\$1,628.00

14 TO REPAIR DAMAGE

1.00

\$680.00

15 TO SPRAY PAINTING

1.00

\$780.00

Subtotal w/o GST:

\$3,088.00

Issued by Elaine Lee

This is a computer-generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: