




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: GARNET LOW			Ref: CS3/ASM22005492/Ttcm4 Date: 20/06/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	CB 6872P	Veh. Inspected	YP 2212L
	Policy No.	VFX/P2420649/00119	Coverage (\$)	0.00
	Claim No.	S2M043L3	Excess (\$)	0.00
	Assign From	GARNET LOW	Assign Date	09/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	HINO XZU710R	c.c	4009
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHHUCS3H40K016256	Colour	WHITE
	Odometer	368723 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	7.00/ R16	CONDOR	6 mm
	L/H Front Tyre	7.00/ R16	CONDOR	6 mm
	R/H Rear Tyre	7.00/ R16 (D)	CONDOR	6/6 mm
	L/H Rear Tyre	7.00/ R16 (D)	CONDOR	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5. General Information				
	Accident Date	06/06/2022	Inspect Date / Time	09/06/2022 (03:40 PM)
	Survey held at	TAMPINES AUTO SERVICE BLK 9002 TAMPINES ST 93 #01-34/36 SINGAPORE 528836		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$7,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

Report Ref No. CS3/ASM22005492/Ttcm4

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.