

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAI	NCE BHD		Ref:	CS3/LPC22005495/y3	
	300 BEACH ROAD #17-04/07 THE CC) NCOURSESINGAPORE 199555		Date:	09/06/2022	
				Code:	LPC2	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBE 9086T	Veh. Inspected		WC 2187T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		09/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	04/06/2022	Inspection Date	е		
	Survey held at					
		160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722				
5a.						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					