



**Section A - Accident Details**

Registration Number	SHB765X
Case Reference Number	TAX/06/22/2028
Registration Date	10/12/2014
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ABDUL SAMAD BIN YUNOS
Type of Accident	Others
Accident Date and Time	7/6/2022 6:05 PM
Accident Reported Date and Time	8/6/2022 12:09 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115244, 24115737
Special Instruction to ARC, if any	DAMAGE TO RIGHT FRONT DOOR
Prepared Date and Time	8/6/2022 2:32 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$250.00
Total Spray Cost	\$558.00	\$270.00
Total Spare Part Cost	\$2,651.80	\$719.52
Total Other Cost	\$500.00	\$100.00
<b>TOTAL COST</b>	<b>\$4,385.80</b>	<b>\$1,339.52</b>
<b>Lump Sum Total</b>	<b>\$4,400.00</b>	<b>\$1,350.00 - \$1050.00 (REPAIR COST EXCEED SALVAGE VALUE BEARED BY STRIDES TAXI) = \$300.00 (L/S)</b>
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Rasul (LKK) / ERGO
ARC / Surveyor Sign Off Date	16/06/2022 12:03 PM	16/06/2022 9:52 AM
Signature		
Remarks	request NBV Total number of repair days = 3 days. SUP = 0 day.	resurvey after repair / lump sum

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-2207-0006, QN-2207-0402	Invoice Number	
Quotation Date	01.07.2022, 27.07.2022	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$250.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$250.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$70.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$558.00</b>	<b>\$270.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$500.00</b>	<b>\$100.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace
			STICKER STRIDES TAXI ( DOOR )	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		68730-12120	HINGE LOWER RHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given
		68710-12151	HINGE UPPER RHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given
		75710-47021	DOOR BELT FRT/RH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check
		85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Not Given
		75755-47020	MOULDING, FR DOOR WINDOW RH	0.00	\$53.70	0.00	\$0.00	Replace	Check
		87910-47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given
		879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	100.00	\$0.00	Replace	Repair
<b>Total</b>					<b>\$3,985.30</b>		<b>\$730.80</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1.00	\$224.80	25.00	\$168.60	Replace	Replace
<b>Total</b>					<b>224.80</b>		<b>168.60</b>		

	899.40		
	-20%	L/S	1,350.00
	719.52	-	1,050.00
+	250.00		300.00
+	370.00		
	1,339.52		