

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005507/ENY3E2**Date:** 14/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00012452100
Claimant Vehicle No :	SLG8843C	Insured Vehicle No :	SNC4283S
Date of Loss:	14/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203798/02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG8843C	Engine No:	2ZRR956945
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU803536370
Reg. Date:	18/10/2016 (Man. Year: 2016)	Odometer:	647421 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,977.75	989.07	988.68	49.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	420.00	930.00	68.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,327.75	1,409.07	1,918.68	57.66
Approved Total (Overridden) (S\$)		1,150.00		
	(S\$)	3,327.75	1,150.00	2,177.75
	+ GST 7.00/7.00% (S\$)	232.94	80.50	152.44
	Nett Amount (S\$)	3,560.69	1,230.50	2,330.19

INSPECTION

Date of Assignment:	08/06/2022		
Date Inspected:	10/06/2022	Inspected At:	Lion City Rentals Pte Ltd (HQ) No 4 Jln Besut Singapore 619557
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2023)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG8843C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	423.90 FL	*423.90 FL
2	1		*REAR BUMPER CENTER PAD	Cut	552.30 FL	*552.30 FL
3	2		*REAR BUMPER LH / RH RETAINER	Not Necessary	225.40 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 FL	*- FL
5	1		*REAR BUMPER LOWER COVER	Not Necessary	303.90 FL	*- FL
6	1		*REAR BUMPER LH / RH SIDE EXTENSION FILTER	Not Necessary	296.80 FL	*- FL
7	1		*REAR BUMPER TOW COVER	Missing	35.90 FL	*35.90 FL
8	1		*SET BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
9	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,517.00	1,242.10
- List Item Discount on L Items 25.00/25.00% (\$)	539.25	253.03
Total Parts (\$)	1,977.75	989.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER, REAR BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	750.00	200.00
2	TO RESPRAY REAR BUMPER AND LH SIDE FILLER	New	600.00	220.00
Gross Labour Cost (\$)			1,350.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >