

SNGAHTEE

MOTOR & PANEL SERVICE

孙亚弟汽车烧焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4 lines) FAX: 62681429 | www.sngahtee.com
sngahtee@singnet.com | UEN / GST REG. NO.: 200810440N

Steve (CLKK)
10/6/22, 12:00pm

00-M
EXC 11-?
LIS
Lj M g
18 djs

C/O UNITED OVERSEAS INSURANCE LIMITED

146 Robinson Road #02-01
UOI Building (S) 068909

ATTENTION :

CONTACT : 6222 7733

FAX NO: 6327 3869/ 6327 3872

EST/QUOTE NO. SQ007397

DATE : 09/06/2022
ACCIDENT DATE : 02/06/2022
VEHICLE NO : PC2424S
CHASSIS/ENG.NO : JTFST22P600018743
VEHICLE MODEL : TOYOTA HIACE
CLAIM NO :
POLICY NO : DHOM110166501903
REMARK

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
							----- SUB-TOTAL: 0.00
** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE / BT	25.00		25.00	25.00
2	1	PC	COOLANT / MCC	40.00		40.00	40.00
							----- SUB-TOTAL 65.00
** COST PLUS MARKUP **							
1	1	PC	FRT BUMPER / BR	170.00	-10.00	187.00	187.00
2	1	PC	FRT BUMPER LWR CENTER GRILLE - BR	90.00	-10.00	99.00	99.00
3	2	PC	FRT BUMPER LWR SIDE GRILLE - BR	40.00	-10.00	44.00	88.00
4	2	PC	FRT BUMPER RETAINER / BR	55.00	-10.00	60.50	121.00
5	2	PC	FRT BUMPER TOWING COVER - BR	15.00	-10.00	16.50	33.00
6	1	PC	FRT BUMPER UPPER CTR REINF - BT	120.00	-10.00	132.00	132.00
7	1	PC	FRT BUMPER REINFORCEMENT - BT	150.00	-10.00	165.00	165.00
8	2	PC	FRT BUMPER UPPER REINF BRKT - BT	70.00	-10.00	77.00	154.00
9	2	PC	FRT BUMPER UPPER REINF ARM - BT	75.00	-10.00	82.50	165.00
10	1	PC	FRT BUMPER UNDER COVER - BR	70.00	-10.00	77.00	77.00
11	10	PC	FRT BUMPER CLIPS - MCC	1.00	-10.00	1.10	11.00
12	1	PC	FRT GRILLE BASE - BR	190.00	-10.00	209.00	209.00
13	1	PC	FRT GRILLE OUTER TOP MOULDING - BR	150.00	-10.00	165.00	165.00
14	1	PC	FRT GRILLE OUTER LWR MOULDING - BR	150.00	-10.00	165.00	165.00

JANICE

PAGE: 1 of 5

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

C/O UNITED OVERSEAS INSURANCE LIMITED

146 Robinson Road #02-01
 UOI Building (S) 068909

ATTENTION :

CONTACT : 6222 7733

FAX NO: 6327 3869/ 6327 3872

EST/QUOTE NO. SQ007397

DATE : 09/06/2022
 ACCIDENT DATE : 02/06/2022
 VEHICLE NO : PC2424S
 CHASSIS/ENG.NO : JTFST22P600018743
 VEHICLE MODEL : TOYOTA HIACE
 CLAIM NO :
 POLICY NO : DHOM110166501903
 REMARK :

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
15	10	PC	FRT GRILLE CLIPS - MK	1.00	-10.00	1.10	11.00
16	1	PC	FRT BONNET - OD	240.00	-10.00	264.00	264.00
17	2	PC	FRT BONNET HINGE - BT	25.00	-10.00	27.50	55.00
18	1	PC	FRT BONNET STAND - BT	25.00	-10.00	27.50	27.50
19	1	PC	FRT BONNET STAND CLIPS - BR	1.00	-10.00	1.10	1.10
20	1	PC	FRT BONNET LOCK - BT	70.00	-10.00	77.00	77.00
21	1	PC	FRT BONNET LOCK CABLE - CUT	70.00	-10.00	77.00	77.00
22	1	PC	FRT BONNET EMBLEM - HA	25.00	-10.00	27.50	27.50
23	2	PC	FRT CORNER PANEL - OD (LH)	70.00	-10.00	77.00	154.00
24	2	PC	FRT CORNER PANEL UPP SIDE CVR (LH) - OD	25.00	-10.00	27.50	55.00
25	2	PC	FRT HEADLAMP - BR	240.00	-10.00	264.00	528.00
26	1	PC	FRT WINDSCREEN - BR	480.00	-10.00	528.00	528.00
27	1	PC	FRT WIPER GARNISH - BR	220.00	-10.00	242.00	242.00
28	2	PC	FRT WIPER GARNISH SIDE COVER (LH) - MS	40.00	-10.00	44.00	88.00
29	2	PC	FRT WIPER ARM (LH) - BT	70.00	-10.00	77.00	154.00
30	2	PC	FRT WIPER BLADE - CUT	25.00	-10.00	27.50	55.00
31	1	PC	FRT WIPER LINKAGE - BT	130.00	-10.00	143.00	143.00
32	1	PC	FRT WIPER PANEL - OD	240.00	-10.00	264.00	264.00
33	1	PC	FRT WIPER PANEL SIDE LH - OD	120.00	-10.00	132.00	132.00
34	1	PC	FRT WIPER PANEL LWR SIDE LH - OD	120.00	-10.00	132.00	132.00
35	1	PC	FRT PANEL OUTER - OD	150.00	-10.00	165.00	165.00
36	1	PC	FRT PANEL ASSY - OD	450.00	-10.00	495.00	495.00
37	1	PC	FRT SUPPORT TOP - OD	150.00	-10.00	165.00	165.00
38	1	PC	FRT SUPPORT LOWER - OD	150.00	-10.00	165.00	165.00

JANICE

PAGE: 2 of 5

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
 Quotation is only valid for 14 days.

C/O UNITED OVERSEAS INSURANCE LIMITED

146 Robinson Road #02-01
 UOI Building (S) 068909

ATTENTION :

CONTACT : 6222 7733

FAX NO: 6327 3869/ 6327 3872

EST/QUOTE NO. SQ007397

DATE : 09/06/2022
 ACCIDENT DATE : 02/06/2022
 VEHICLE NO : PC2424S
 CHASSIS/ENG.NO : JTFST22P600018743
 VEHICLE MODEL : TOYOTA HIACE
 CLAIM NO :
 POLICY NO : DHOM110166501903
 REMARK :

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
39	1	PC	FRT BRACE PANEL / 00	40.00	-10.00	44.00	44.00
40	1	PC	FRT DOOR(LH) / 00	580.00	-10.00	638.00	638.00
41	1	PC	FRT DOOR HINGE(LH)(TOP) / 01	40.00	-10.00	44.00	44.00
42	1	PC	FRT DOOR HINGE(LH)(BOTTOM) / 01	40.00	-10.00	44.00	44.00
43	1	PC	FRT DOOR CHECKER(LH) / 01	70.00	-10.00	77.00	77.00
44	1	PC	FRT DOOR INNER TRIMBOARD LH / 01	380.00	-10.00	418.00	418.00
45	1	PC	FRT DOOR RUBBER(LH) / 01	90.00	-10.00	99.00	99.00
46	1	PC	FRT DOOR LOCK(LH) / 01	150.00	-10.00	165.00	165.00
47	1	PC	FRT DOOR LOCK CABLE(LH) ?	150.00	-10.00	165.00	165.00
48	1	PC	FRT DOOR OUTER HANDLE(LH) ?	70.00	-10.00	77.00	77.00
49	1	PC	FRT DOOR INNER HANDLE (LH)	70.00	-10.00	77.00	77.00
50	1	PC	FRT DOOR GLASS(LH) / 01	180.00	-10.00	198.00	198.00
51	1	PC	FRT DOOR GLASS REGULATOR(LH) / 01	90.00	-10.00	99.00	99.00
52	1	PC	FRT DOOR GLASS MOTOR LH ?	240.00	-10.00	264.00	264.00
53	1	PC	FRT DOOR GLASS INNER MLDG LH / 01	70.00	-10.00	77.00	77.00
54	1	PC	FRT DOOR GLASS OUTER MLDG LH / 01	70.00	-10.00	77.00	77.00
55	1	PC	FRT DOOR GLASS RUN CHANNEL(LH) / 01	90.00	-10.00	99.00	99.00
56	1	PC	FRT DOOR FRAME INNER TRIM LH / 01	320.00	-10.00	352.00	352.00
57	1	PC	FRT SIDE MIRROR ASSY(LH) / 01	270.00	-10.00	297.00	297.00
58	1	PC	FRT DOOR REAR PANEL(LH) / 01	240.00	-10.00	264.00	264.00
59	1	PC	FRT FUEL FILLER COVER LH X	120.00	-10.00	132.00	132.00
60	1	PC	FRT WHEEL HOUSE PANEL(LH) / 01	280.00	-10.00	308.00	308.00
61	1	PC	FRT SCUFF PLATE(LH) ?	90.00	-10.00	99.00	99.00
62	1	PC	FRT PILLAR OUTER(LH) / 01	240.00	-10.00	264.00	264.00

JANICE

PAGE: 3 of 5

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
 Quotation is only valid for 14 days.

C/O UNITED OVERSEAS INSURANCE LIMITED

146 Robinson Road #02-01
 UOI Building (S) 068909

ATTENTION :

CONTACT : 6222 7733

FAX NO: 6327 3869/ 6327 3872

EST/QUOTE NO. SQ007397

DATE : 09/06/2022
 ACCIDENT DATE : 02/06/2022
 VEHICLE NO : PC2424S
 CHASSIS/ENG.NO : JTFST22P600018743
 VEHICLE MODEL : TOYOTA HIACE
 CLAIM NO :
 POLICY NO : DHOM110166501903
 REMARK :

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
63	1	PC	FRT PILLAR INNER(LH) / <i>DD</i>	240.00	-10.00	264.00	264.00
64	1	PC	FRT PILLAR INNER TRIM(LH) / <i>CR4</i>	220.00	-10.00	242.00	242.00
65	1	PC	FRT PILLAR INNER LOWER(LH) ?	120.00	-10.00	132.00	132.00
66	1	PC	FRT STEP PANEL(LH) ?	70.00	-10.00	77.00	77.00
67	1	PC	FRT STEP GARNISH(LH) ?	55.00	-10.00	60.50	60.50
68	1	PC	COOLANT SPARE TANK / <i>CR4</i>	150.00	-10.00	165.00	165.00
69	1	PC	WASHER TANK / <i>CR4</i>	75.00	-10.00	82.50	82.50
70	1	PC	AIRCON CONDENSER / <i>DD</i>	450.00	-10.00	495.00	495.00
71	1	PC	AIRCON HIGH PRESSURE PIPE / <i>RT</i>	190.00	-10.00	209.00	209.00
72	1	PC	AIRCON LOW PRESSURE PIPE ?	190.00	-10.00	209.00	209.00
73	1	PC	RADIATOR ASSY / <i>OR</i>	550.00	-10.00	605.00	605.00
74	1	PC	INTER COOLER ASSY / <i>DD</i>	550.00	-10.00	605.00	605.00
75	1	PC	INTER COOLER HOSE ?	120.00	-10.00	132.00	132.00
76	1	PC	FRT HORN ?	70.00	-10.00	77.00	77.00
77	1	PC	FRT DASHBOARD / <i>OR</i>	400.00	-10.00	440.00	440.00
78	1	PC	FRT DASHBOARD SUPORT BEAM / <i>RT</i>	350.00	-10.00	385.00	385.00
79	1	PC	AIRCON BLOWER / <i>OR</i>	450.00	-10.00	495.00	495.00
80	1	PC	HEATER BLOWER / <i>OR</i>	1,700.00	-10.00	1,870.00	1,870.00
81	1	PC	AIRCON CONDITIONER PANEL ?	120.00	-10.00	132.00	132.00
82	1	PC	AIRCON AIR VENT PANEL ?	120.00	-10.00	132.00	132.00
83	1	PC	FRT GLOVE BOX(LH) / <i>OR</i>	150.00	-10.00	165.00	165.00
84	1	PC	FRT GEAR KNOB PANEL / <i>CR1</i>	240.00	-10.00	264.00	264.00
85	2	PC	FRT AIRBAG SENSOR / <i>M</i>	170.00	-10.00	187.00	374.00
86	1	PC	DRIVER AIRBAG / <i>OR</i>	1,300.00	-10.00	1,430.00	1,430.00

JANICE

PAGE: 4 of 5

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
 Quotation is only valid for 14 days.

C/O UNITED OVERSEAS INSURANCE LIMITED

146 Robinson Road #02-01
 UOI Building (S) 068909

ATTENTION :

CONTACT : 6222 7733

FAX NO: 6327 3869/ 6327 3872

EST/QUOTE NO. SQ007397

DATE 09/06/2022

ACCIDENT DATE : 02/06/2022

VEHICLE NO : PC2424S

CHASSIS/ENG.NO : JTFST22P600018743

VEHICLE MODEL : TOYOTA HIACE

CLAIM NO :

POLICY NO : DHOM110166501903

REMARK :

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
87	1	PC	FRT PASSENGER AIRBAG ✓ <i>OK</i>	1,700.00	-10.00	1,870.00	1,870.00
88	2	PC	FRT SEAT BELT ✓ <i>found</i>	450.00	-10.00	495.00	990.00
89	1	PC	FRT CLOCK SPRING ✓ <i>MC</i>	240.00	-10.00	264.00	264.00
90	1	PC	FRT FLOOR PANEL X <i>R</i>	1,800.00	-10.00	1,980.00	1,980.00
91	1	PC	FRT FLOOR MAT X	800.00	-10.00	880.00	880.00

						SUB-TOTAL	25,180.10

**** WORK LABOUR ****

TO KNOCK RR SLIDING DOOR LH & REPLACE ABOVE PARTS	<i>1400</i>	1600.00	1,600.00
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	<i>800 1200</i>	1400.00	1,400.00
TO CHECK WIRING		30.00 ✓	30.00
TO REMOVE & FIX FRONT WINDSCREEN		120.00 ✓	120.00
TO REMOVE & FIX DASHBOARD	<i>150</i>	180.00	180.00
TO REMOVE & FIX INTERIOR UPHOLSTERY	<i>X</i>	150.00	150.00
TO REMOVE & FIX AIRBAG	<i>200</i>	280.00	280.00
TO DIAGNOSE & PROGRAM AIRBAG SYSTEM	<i>100</i>	200.00	200.00
TO TRANSFER FRT DOOR LH COMPONENT	<i>50</i>	60.00	60.00
TO TOP UP AIRCON GAS		100.00 ✓	100.00
TO KNOCK STRAIGHTEN, JACK FRT CHASSIS LH	<i>200</i>	300.00	300.00
TO REMOVE & FIX FUEL TANK	<i>X</i>	180.00	180.00
TO REDO COMPANY LOGO	<i>180</i>	280.00	280.00

		SUB-TOTAL	4,880.00

JANICE

PAGE: 5 of 5

SUB-TOTAL : S\$ 30,125.10

ADD 7% GST. S\$ 2,108.76

GRAND TOTAL : S\$ 32,233.86

ON BEHALF OF

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be ...
 is subject to final ...

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

Signature:
 Date: